DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	28/10/2026		
Inspection Date	28/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	ND62KHGP
Model	GRAND I10 1.0 MOTION 5-DR [2020-2024]	Register Number	
VIN	MALB251ALNM230814	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model	2021	Paint Finish	C - COMMON
Km Reading	208,709 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Fan Belt Worn	Replace
Center Console / Cubbyhole + Lid Defective	Repair
Electrical Window Winder front right Defective	Repair
Air Conditioner Insufficient	Repair
Seat Front Left Worn	Repair
Seat Front Right Excessive Wear & Tear	Repair
Hood Lining Loose / Excessive Play	Repair
Door Sealing Rubber Front Right Torn / Cut	Replace
Brake Pedal Rubber Missing	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Residual Traces of Repair	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Residual Traces of Repair	Repair
Sill Panel Right Residual Traces of Repair	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Tyre Front Left Smooth	Replace
Rim Front Left Dented	Replace
Rim Rear Right Dented	Repair
Chassis Dented	Repair
Belly plates Cracked	Replace
Radiator Cradle Damaged	Repair
BODY EXTERIOR	signs of impact damage to front & back of vehicle
Airbag light illuminated	Repair
Rear tyres differs in size	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.6	2.4	-	
Rear	1.7	1.7	-	
Emergency / Parking	1.2	1	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82T	DUNLOP	SP SPORT	V	4123	2 mm
Front Right	175/65R14	82T	DUNLOP	SP SPORT	V	4723	3 mm
Rear Left	175/65R14	82T	DUNLOP	SP SPORT	V	4523	4 mm
Rear Right	165/70R14	81T	GOODYEAR	ASSURANCE	V	3321	3 mm
Spare	175/65R14	82T	DUNLOP	SP SPORT	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0011	INTAKE CAMSHAFT POSITION CMP ATIMING OVER ADVANCE OR SYSTEM PERFORMANCE (BANK 1)	ACTIVE

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of poor repairs below standard.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814


DEKRA

CONDITION REPORT


Report No:
2017318755
DATE
28/10/2026



Brake report



DIAGNOSTICS



DIAGNOSTICS



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT


Report No:
2017318755
DATE
28/10/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



No license disc



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



CHASIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



OIL CAP AND DIPSTICK



Seat Front Left




Seat Front Left



Seat Front Right



Water level



Rim Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814


DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Rim Front Left



Tyre Front Left



Engine



Fan Belt



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Chassis



Sill Panel Left




Sill Panel Right



Sill Panel Right



Belly plates



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Front Bumper



Front Bumper




Front Bumper



Front Bumper



Door Front Right



Door Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT


Report No:
2017318755
DATE
28/10/2026




Rear Fender Right



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Boot Lid / Hatch door




Boot Lid / Hatch door




Rear Fender Left



Door Rear Left



Door Front Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Rear Fender Left




Door Rear Left



Door Front Left



Door Front Left



Front Fender Left



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Roof



Fan Belt




Bonnet



Windscreen



Windscreen



Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Door Sealing Rubber Front Right




Door Rear Right



Brake Pedal Rubber



Air Conditioner



Center Console / Cubbyhole + Lid



Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814

DEKRA

CONDITION REPORT

Report No:
2017318755
DATE
28/10/2026



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALNM230814