DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	LB67DPGP
Model	I20 1.2 MOTION 5-DR [2021-2024]	Register Number	
VIN	MALBG512LPM196131	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	GREY	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	111,155 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No: 2017315252
DATE 21/10/2026



Damage	Repair Way
Seat Front Right Excessive Wear & Tear	Repair
Door Sealing Rubber Front Left Worn	Replace
Door Sealing Rubber Front Right Excessive Wear & Tear	Replace
Door Sealing Rubber Rear Left Excessive Wear & Tear	Replace
Door Lock Boot Lid Defective	Repair
Side Mirror Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Dented	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Residual Traces of Repair	Repair
Windscreen Chipped	Repair
Belly plates Damaged	Replace
Warning light illuminated	Repair
Boot lid/hatch door not opening	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.6	-	
Rear	1.7	1.7	-	
Emergency / Parking	1	1.1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Annaite	An600	V	0125	4 mm
Front Right	185/65R15	88H	Annaite	An600	V	0125	4 mm
Rear Left	185/65R15	88H	Bridgestone	Ecopia	V	4922	4 mm
Rear Right	185/65R15	88H	Bridgestone	Ecopia	V	4922	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P2237:00	OXYGEN SENSOR PUMPING CURRENT CIRCUIT/OPEN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.RESIDUAL TRACES OF POOR REPAIR (REPAIRS DONE BELOW STANDARD)

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



ENGINE 1



ENGINE 2




CHASSIS



REAR



Oil cap and dipstick



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131


DEKRA

CONDITION REPORT


Report No:
2017315252
DATE
21/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Brake report



Diagnostic Report page 1



Diagnostic Report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



Door Lock Boot Lid


Water level


Bonnet slam plate (Shock tower/ Inner tray)


Front Bumper


Front Bumper


Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131


DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



Front Fender Left




Windscreen



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT


Report No:
2017315252
DATE
21/10/2026



Rear Fender Left



Rear bumper




Rear bumper



Rear Fender Right



Door Rear Right



Door Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



Bonnet



Belly plates



Belly plates



Front Bumper



Front Bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131


DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026




Seat Front Right



Door Sealing Rubber Front Right



Door Sealing Rubber Front Right



Door Sealing Rubber Rear Left



Door Sealing Rubber Front Left



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131

DEKRA

CONDITION REPORT

Report No:
2017315252
DATE
21/10/2026



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG512LPM196131