CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	HP32SYGP
Model	I20	Register Number	
VIN	MALBM51BLKM516025	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/03/2026
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	182,859 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026





Damage	Repair Way
Fan Belt Torn / Cut	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Side Mirror Right Paintwork • Chipmarks	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Residual Traces of Repair	Repair
B • Pillar Right Residual Traces of Repair	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Residual Traces of Repair	Repair
Sill Panel Right Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Front Right Damaged	Replace
Tyre Rear Right Torn / Cut	Replace
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Chassis Damaged	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Replace
Boot does not open	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.36	2.9	-	
Rear	2.35	2.37	-	
Emergency / Parking	1.17	0.99	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55 R16	87V	Nexen	Nblue	V	4522	2 mm
Front Right	195/55 R16	87V	Nexen	Nblue	V	4522	1 mm
Rear Left	195/55 R16	87V	Nexen	Nblue	V	4522	4 mm
Rear Right	195/55 R16	87H	Michelin	Primacy 4	V	2519	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Lights: Front left and right headlight lenses faded.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of hail damage on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



90 DEGREE RIGHT



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



ENGINE 1



Oil cap and dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Front chassis




Rear chassis



RR TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025


DEKRA

CONDITION REPORT


Report No:
2017314859
DATE
21/10/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



LICENSE DISC



VIN PLATE OR STICKER



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Seat Front Right




C • Pillar Right



B • Pillar Right



Rear Fender Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Door Front Right



Front Fender Right



Side Mirror Right



Tyre Front Right



Bolt(s) / Nut(s) Front Wheel Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Bolt(s) / Nut(s) Front Wheel Left



Windscreen




Door Front Left



Door Rear Left



Rear Fender Left



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right



Tyre Rear Right



Roof



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Boot Lid / Hatch door




Fan Belt



Headlight Left



Headlight Right



Front Fender Right / Inner Tray



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Front Bumper


Front Bumper


Front Bumper


Sill Panel Left


Rim Rear Left


Rear Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025

DEKRA

CONDITION REPORT

Report No:
2017314859
DATE
21/10/2026



Sill Panel Right



Belly plates



Chassis



Chassis



Radiator Cradle



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM516025