DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	JK87RMGP
Model	I20 1.2 MOTION 5-DR [2018-2021]	Register Number	
VIN	MALBM51BLLM726496	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2025
Color	SILVER	Power / Displacement	
Year Model	2020	Paint Finish	TWO COAT UNI
Km Reading	205,930 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Fan Belt Torn / Cut	Replace
Switch Electrical Window Winder front left Malfunction	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Front Fender Right / Inner Tray Residual Traces of Repair	Repair
Door Front Left Dented	Repair
Door Rear Left Dented	Repair
Rear bumper Damaged	Repair
Sill Panel Left Dented	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Worn	Replace
Spare Tyre Worn	Replace
Main Beam Left Dented	Repair
Chassis Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	2.34	2.49	-	
Rear	2.13	2.07	-	
Emergency / Parking	1.08	1.23	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70 R14	88T	Goodyear	Assurance	V	2619	0 mm
Front Right	185/70 R14	88H	Campiro	GT Radial	V	2921	0 mm
Rear Left	185/70 R14	88H	Campiro	GT Radial	V	4821	0 mm
Rear Right	185/70 R14	88H	Campiro	GT Radial	V	4821	1 mm
Spare	185/70 R14	88H	Campiro	GT Radial	V	3921	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0030	HEATED OXYGEN SENSOR(HO2S) HEATER CONTROL CIRCUIT(	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



90 DEGREE RIGHT



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Spare wheel and Accessories



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026




ENGINE 1




Front chassis




Rear chassis



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496


DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



Rear Fender Left



Door Rear Left



Door Front Left



Rear bumper



Rear bumper



Spare Tyre


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT


Report No:
2017315455
DATE
21/10/2026



Rear Fender Right



Side Mirror Right



Front Fender Right



Bonnet



Switch Electrical Window Winder front left



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026




Front Fender Right / Inner Tray



Fan Belt



Main Beam Left



Rear bumper



Sill Panel Left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



Front Bumper



Front Bumper



Engine



Chassis



Tyre Rear Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496

DEKRA

CONDITION REPORT

Report No:
2017315455
DATE
21/10/2026



Tyre Front Left



Chassis



Water level



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLLM726496