# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572




## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 20/10/2026 | | |
| Inspection Date | 20/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | HYUNDAI | Registration Number | JN28GXGP |
| Model | VENUE 1.0 88KW TGDI MOTION INFOTAINMENT AT [2021-2023] | Register Number | |
| | | Date Of First Licensing | |
| VIN | MALFB81AVLM053659 | Last COR | |
| Engine Number | | License Expiry Date | 31/07/2026 |
| Doors | 5 | Power / Displacement | |
| Color | RED | Paint Finish | C - COMMON |
| Year Model | 2020 | Fuel | PETROL |
| Km Reading | 219,707 KM | Transmission | AUTOMATIC |
| Cab / Body Type | HATCHBACK | | |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**





| Damage | Repair Way |
|---|---|
| Engine Oil Leak | Repair |
| Hoses Oil Leak | Repair |
| Center Console / Cubbyhole + Lid Damaged | Repair |
| Door Sealing Rubber Front Left Torn / Cut | Replace |
| Door Sealing Rubber Front Right Torn / Cut | Replace |
| Door Sealing Rubber Rear Left Torn / Cut | Replace |
| Door Sealing Rubber Rear Right Torn / Cut | Replace |
| Front Bumper Paintwork • Scratched | Repair |
| Bonnet Dented | Repair |
| Front Fender Left Paintwork • Scratched | Repair |
| Front Fender Right Paintwork • Scratched | Repair |
| Rear Fender Left Dented | Repair |
| Rear Fender Right Dented | Repair |
| Door Front Left Dented | Repair |
| Door Front Right Dented | Repair |
| Door Rear Left Paintwork • Scratched | Repair |
| Door Rear Right Dented | Repair |
| Boot Lid / Hatch door Dented | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Roof Dented | Repair |
| Windscreen Chipped | Replace |
| Tyre Front Left Worn | Replace |
| Tyre Front Right Worn | Replace |
| Tyre Rear Right Smooth | Replace |
| Gearbox Oil Leak | Repair |
| Steering Noisy | Repair |
| Jack Missing | Replace |
| Wheel Spanner Missing | Replace |
| Triangle Missing | Replace |
| Ignition Coil Pack missing bolt | Repair |
| Computer box loose. | repair |
| Sparewheel missing | Replace |
| Rear left and right tyre sizes different | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.3 | 2.5 | - | |
| **Rear** | 1.4 | 1.2 | - | |
| **Emergency / Parking** | 0.8 | 0.8 | - | |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 195/65R15 | 91V | Dunlop | Sport FM800 | V | 0725 | 0 mm |
| **Front Right** | 195/65R15 | 91V | Dunlop | Sport FM800 | V | 0725 | 0 mm |
| **Rear Left** | 195/65R15 | 91H | Anchee | AC808 | V | 0925 | 3 mm |
| **Rear Right** | 205/60R15 | 91V | MIRAGE | MR 162 | V | 2517 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | ENGINE | P2565:00 | TURBOCHARGER BOOST CONTROL POSITION SENSOR A CIRCIT HIGH | ACTIVE |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: 1st Ignition Coil Pack missing bolt Battery loose
Electrical Components and Instruments: Warning lights illuminated
Body • Exterior: Dents and scratches on body panels.Body panels misaligned.
Loose Items (Jack, Wheel Spanner, etc.): Spare wheel missing.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659


DEKRA

# CONDITION REPORT


**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Brake Test



Diagnostics



Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**




DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



Automatic




90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659


DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**




90 DEGREE LEFT




LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD




LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**




VIN PLATE OR STICKER


ENGINE 1


ENGINE 2


CHASSIS


Chassis 2


Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Ignition Coil Pack



ECU Bracket



Engine



Water level



Water level



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Windscreen



Windscreen



Door Front Right



Door Front Left



Door Rear Left



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Rear bumper


Rear bumper


Rear bumper


Jack


Wheel Spanner


Triangle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT


**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear Fender Right



Rear Fender Right



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Rear Fender Left



Front Fender Left



Front Fender Left



Front Fender Right



Front Fender Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Bonnet




Front Bumper




Front Bumper



Front Bumper



Roof



Hoses


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT


**Report No:**
**2017314527**
**DATE**
**20/10/2026**




Hoses



Gearbox



Tyre Front Right



Tyre Front Left



Tyre Rear Right



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659

DEKRA

# CONDITION REPORT

**Report No:**
**2017314527**
**DATE**
**20/10/2026**



Door Sealing Rubber Front Right



Door Sealing Rubber Rear Right



Door Sealing Rubber Rear Left



Door Sealing Rubber Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVLM053659