CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	05/10/2026		
Inspection Date	05/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	JZ46LRGP
Model	VENUE 1.0 88KW TGDI MOTION INFOTAINMENT AT [2021-2023]	Register Number	
		Date Of First Licensing	
VIN	MALFB81AVMM169859	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	RED	Paint Finish	TWO COAT UNI
Year Model	2021	Fuel	PETROL
Km Reading	119,041 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026





Damage	Repair Way
Hoses Oil Leak	Replace
Fan Belt Torn / Cut	Replace
Air conditioner pipes Damaged	Repair
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Missing	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Door Lock Front Right Damaged	Replace
Boot Carpet Damaged	Repair
Side Mirror Right Residual Traces of Repair	Replace
Front Bumper Damaged	Replace
Bonnet Dented	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Damaged	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Rim Front Right Dented	Repair
Rim Spare Wheel Dented	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Replace
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Warning light illuminated on dashboard	Repair
Vehicle license disk missing only operator card	Replace
Radiator and Aircon condenser misaligned.	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No: 2017307436
DATE 05/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.05	2.97	-	
Rear	2.03	2.13	-	
Emergency / Parking	1.31	1.51	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65 R15	91H	Goodyear	Assurance	V	0721	1 mm
Front Right	195/65 R15	91H	Goodyear	Assurance	V	0721	0 mm
Rear Left	195/65 R15	91H	Goodyear	Assurance	V	0621	2 mm
Rear Right	195/65 R15	91H	Goodyear	Assurance	V	0721	1 mm
Spare	195/65 R15	91H	Goodyear	Assurance	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI-LOCK BRAKE/ELECTRONIC STABILITY PROGR	C1623:08	CAN TIMEOUT-STEERING ANGLE SENSOR(SAS)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.VEHICLE INTERIOR DIRTY AND PANELS SCRATCHED / POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / DENTS AND SCRATCHES ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT OF VEHICLE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge,

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026

operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



NO LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859


DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859


DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026




LR TYRE TREAD




RR TYRE TREAD




Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859


DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Door Sealing Rubber Front Right




Seat Front Right



Seat Front Right



Door Sealing Rubber Rear Right



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026




Side Mirror Right



Hood Lining



Rear Fender Right



Door Front Right



Front Fender Right



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Rear bumper




Rear Fender Left



Door Rear Left



Door Sealing Rubber Rear Left



Door Sealing Rubber Front Left



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Door Front Left



Front Fender Left



Windscreen



Bonnet



Spare Tyre



Rim Spare Wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Boot Carpet



Boot Lid / Hatch door



Boot Lid / Hatch door



Roof



Front Fender Right / Inner Tray



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT


Report No:
2017307436
DATE
05/10/2026



Front Bumper


Front Bumper


Headlight Right


Front Bumper


Rear Fender Left / Inner Tray


Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Radiator Cradle



Air conditioner pipes



Hoses



Tyre Front Right



Tyre Front Left



Fan Belt

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859

DEKRA

CONDITION REPORT

Report No:
2017307436
DATE
05/10/2026



Rim Front Left



Engine to silencer pipe



Water level



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81AVMM169859