DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 26/10/2026 | | |
| Inspection Date | 26/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | SUZUKI | Registration Number | JB62NGGP |
| Model | SWIFT 1.2I GL 5-DR AT [2018-2021] | Register Number | |
| VIN | MBHCZC63S00391462 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/10/2025 |
| Color | GREY | Power / Displacement | |
| Year Model | 2019 | Paint Finish | C - COMMON |
| Km Reading | 83,696 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | AUTOMATIC |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**





| Damage | Repair Way |
|---|---|
| Windscreen Wiper Worn | Replace |
| Air Conditioner Insufficient | Repair |
| Dim Light Left Defective | Replace |
| Fog Light Front Right Defective | Replace |
| Door Sealing Rubber Front Left Damaged | Replace |
| Carpet Rear Defective | Repair |
| Front Bumper Residual Traces of Repair | Repair |
| Bonnet Residual Traces of Repair | Repair |
| Front Fender Left Dented | Repair |
| Front Fender Right Residual Traces of Repair | Repair |
| Rear Fender Left Residual Traces of Repair | Repair |
| Rear Fender Right Residual Traces of Repair | Repair |
| Front Fender Left / Inner Tray Damaged | Replace |
| Front Fender Right / Inner Tray Damaged | Replace |
| Door Front Left Residual Traces of Repair | Repair |
| Door Front Right Residual Traces of Repair | Repair |
| Door Rear Left Residual Traces of Repair | Repair |
| Door Rear Right Residual Traces of Repair | Repair |
| Boot Lid / Hatch door Damaged | Repair |
| Rear bumper Damaged | Repair |
| Sill Panel Left Residual Traces of Repair | Repair |
| Sill Panel Right Residual Traces of Repair | Repair |
| Windscreen Chipped | Repair |
| Service Brake Performance Rear Axle Insufficient | Repair |
| Tyre Front Right Smooth | Replace |
| Spare Tyre Smooth | Replace |
| Main Beam Left Damaged | Repair |
| Main Beam Right Damaged | Repair |
| Radiator Cradle Damaged | Replace |
| Rear tyres size differs | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.1 | 2.6 | - | |
| **Rear** | 0.9 | 0.9 | - | |
| **Emergency / Parking** | 0.4 | 0.5 | - | |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 165/80R14 | 85T | APOLLO | AMAZER | V | 1019 | 3 mm |
| **Front Right** | 165/80R14 | 85T | APOLLO | AMAZER 3G | V | 0919 | 1 mm |
| **Rear Left** | T135/70R15 | 99M | STAR XT | TEMPORARY | V | 1019 | 5 mm |
| **Rear Right** | 165/80R14 | 85T | APOLLO | AMAZER | V | 0000 | 4 mm |
| **Spare** | 165/80R14 | 85T | Apollo | Amazer 3G | V | 1119 | 1 mm |

* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | ABS/ESP(ANTI-LOCK BRAKING SYSTEM | C1057 | POWER SUPPLY VOLTAGE | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Body has excessive residual traces of poor repair below standard.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462


DEKRA

# CONDITION REPORT


**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Brake report



Diagnostics



Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



AUTOMATIC




90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462


DEKRA

# CONDITION REPORT


**Report No:**
**2017317349**
**DATE**
**26/10/2026**



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**




LICENSE DISC





VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



CHASIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Oil cap and dipstick



Spare Tyre



Windscreen Wiper



Windscreen Wiper



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Front Bumper


Front Bumper


Front Bumper


Front Fender Right


Rear Fender Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Door Rear Right





Boot Lid / Hatch door



Boot Lid / Hatch door




Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Rear Fender Left



Rear bumper




Door Rear Left



Door Front Left



Front Fender Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Bonnet



Door Sealing Rubber Front Left



Carpet Rear




Air Conditioner



Fog Light Front Right



Dim Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462


DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Water level



Tyre Front Right



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



Main Beam Left



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462

DEKRA

# CONDITION REPORT

**Report No:**
**2017317349**
**DATE**
**26/10/2026**



Radiator Cradle




Radiator Cradle



Sill Panel Right



Sill Panel Left



Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00391462