DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	SUZUKI	Registration Number	KT75YPGP
Model	SWIFT 1.2I GA 5-DR [2021-2025]	Register Number	
VIN	MBHCZC63S00A21310	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2027
Color	SILVER	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	79,413 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Battery box Damaged	Replace
Air cleaner Defective	Repair
Bonnet hinges Damaged	Replace
Bonnet stay and shocks Missing	Replace
Central Air Vent Damaged	Replace
Radio/CD/USB Missing	Replace
Air Conditioner Insufficient	Replace
Tail Light Left Cracked	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Right Damaged	Repair
Parcel Tray Damaged	Replace
Side Mirror Right Residual Traces of Repair	Repair
Front Bumper Damaged	Replace
Grill Cracked	Replace
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Left Dented	Repair
Front Fender Left Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Weather Strip Door Front Right Damaged	Replace
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Left Dented	Repair
Roof Dented	Repair
Tyre Front Left Worn	Replace
Spare Tyre Damaged	Replace
Rim Rear Right Dented	Repair
Rim Spare Wheel Damaged	Repair
Main Beam Left Welded	Repair
Chassis Damaged	Repair
Cross Member Rear Left Damaged	Repair
Sub Frame Damaged	Replace
Gearbox Oil Sweat	Repair
Radiator Cradle Damaged	Repair
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Left side mirror missing	Replace
Fan Cowley damaged	Replace
Left wiper valance plastic cover missing	Replace
Front and rear tyre sizes different	Repair
Battery loose	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No: 2017316614
DATE 23/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.99	2.07	-	
Rear	1.15	1.33	-	
Emergency / Parking	1.08	1.14	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	82T	Falken	Sincera	V	2422	0 mm
Front Right	185/70 R14	88H	Hilo	Genesys	V	0922	1 mm
Rear Left	185/70 R14	88T	Hilo	Genesys	V	0922	3 mm
Rear Right	T135/70 R15	99M	Jk tyre	Temporary	V	1522	3 mm
Spare	185/70 R14	88T	Hilo	Geneys	V	0922	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI-LOCK BRAKING SYSTEM/ELECTRONIC STABIL	C1057	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.FRONT LEFT INNER FENDER LINER MISSING / POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT OF VEHICLE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



ENGINE 1



Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026




LR TYRE TREAD




RR TYRE TREAD




Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Fan Cowley



Seat Front Right



A • Pillar Right



Rear Fender Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Door Front Right




Tail Light Right



Tail Light Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Rear Fender Left




Door Rear Left



Door Rear Left



Door Front Left



Front Fender Left



B • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Central Air Vent



Air Conditioner



Bonnet



Parcel Tray



Rim Spare Wheel



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Radio/CD/USB



Bonnet stay and shocks



Bonnet hinges



Battery box



Bonnet slam plate (Shock tower/ Inner tray)



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Air cleaner



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Right / Inner Tray



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT


Report No:
2017316614
DATE
23/10/2026



Front Bumper



Grill



Main Beam Left



Radiator Cradle



Sill Panel Left



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Tyre Front Left



Main Beam Left



Radiator Cradle



Gearbox



Sub Frame



Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Front Fender Left / Inner Tray



Chassis



Chassis



Chassis



Cross Member Rear Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310

DEKRA

CONDITION REPORT

Report No:
2017316614
DATE
23/10/2026



Water level



Side Mirror Right



Engine



Weather Strip Door Front Right



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00A21310