DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	SUZUKI	Registration Number	LW14WKGP
Model	SWIFT 1.2I GA 5-DR [2021-2025]	Register Number	
VIN	MBHCZC63S00E09902	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2026
Color	WHITE	Power / Displacement	
Year Model	2024	Paint Finish	M - METALLIC
Km Reading	82,571 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Tail Light Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Dented	Repair
Rear Fender Left / Inner Tray Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Inner Boot Floor Pan and Spare Wheel Well Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Tyre Front Left Smooth	Replace
Radiator Cradle Dented	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Signs of spray work done on some body panels
L/R tire deferred name brand and size	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	2.3	2.2	-	
Rear	1.0	1.1	-	
Emergency / Parking	0.9	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/80R14	85T	Apollo	Amazer	V	0124	0 mm
Front Right	165/80R14	85T	Apollo	Amazer	V	0224	2 mm
Rear Left	175/65R14	82H	Joy road	Tour rx1	V	3723	3 mm
Rear Right	165/80R14	85T	Apollo	Amazer	V	0125	3 mm
Spare	T135/70R15	99M	Jk tyre	Temporary	V	0124	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	C1057	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



90 DEGREE RIGHT




Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Coolant bottle



Oil cap and dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



ENGINE 1



ENGINE 2



CHASSIS



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT


Report No:
2017315456
DATE
21/10/2026




RF TYRE TREAD




Spare wheel



Shock and brake report



Diagnostic report



Diagnostic report



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



VIN PLATE OR STICKER



Windscreen



Water level



Inner Boot Floor Pan and Spare Wheel Well



Tail Light Left



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



Rear bumper



Rear bumper



Rear Fender Left



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



Front Bumper



Front Bumper




Front Fender Right



Door Front Right



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902

DEKRA

CONDITION REPORT

Report No:
2017315456
DATE
21/10/2026



Engine



Radiator Cradle



Radiator Cradle



Tyre Front Left



Inner Boot Floor Pan and Spare Wheel Well



Rear Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00E09902