DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	SUZUKI	Registration Number	KS80LSGP
Model	DZIRE 1.2 GA MC [2020-2025]	Register Number	
VIN	MBHCZF63S00264853	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	GREY	Power / Displacement	
Year Model	2022	Paint Finish	C - COMMON
Km Reading	216,891 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026





Damage	Repair Way
Engine Water Leak	Repair
Headlight Right Damaged	Repair
Door Sealing Rubber Rear Left Missing	Replace
Door Sealing Rubber Rear Right Defective	Repair
Carpet Rear Damaged	Replace
Front Bumper Damaged	Repair
Front Fender Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Windscreen Cracked	Replace
Tyre Front Right Torn / Cut	Replace
Tyre Rear Right Defective	Repair
Main Beam Right Damaged	Repair
Sub Frame Dented	Repair
Belly plates Damaged	Replace
Radiator Cross Member Damaged	Repair
Front right Head light bracket damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.9	1.9	-	
Rear	1.2	1.3	-	
Emergency / Parking	0.7	0.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/80R14	85T	Apollo	Amazer	V	4021	1 mm
Front Right	165/80R14	85T	Apollo	Amazer	V	4723	4 mm
Rear Left	165/60R14	85T	Apollo	Amazer	V	4723	3 mm
Rear Right	165/80R14	85T	Apollo	Amazer	V	0224	4 mm
Spare	T135/70R15	99m	Jktyre	Staraxt	V	3323	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM/PCM ENGINE/POWERTRAIN	P0480	FAN 1 CONTROL CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF IMPACT TO FRONT VEHICLE / SPAREWHEEL WELL FULL OF WATER / SOME BODY PANELS NEEDS ALIGNMENT / RESIDUAL TRACES OF POOR REPAIR BELOW STANDARD / RIGHT FRONT MAIN BEAM SUSPECTED SIGNS OF HEATING / THE BODY HAS DENTS SCRATCHES STONE CHIPS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



ENGINE 1




ENGINE 2




CHASSIS



Chasis



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Sparewheel



Brake report



Diagnostics


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026




Diagnostics



Sparewheel well



Front right Main beam



Tyre Front Right



Tyre Front Right



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853


DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



Rear bumper



Rear bumper




Engine



Tyre Rear Right



Belly plates



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



Front Fender Right / Inner Tray



Radiator Cross Member



Sub Frame



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



Front Bumper



Windscreen



Windscreen



Headlight Right



Front Bumper



Door Sealing Rubber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853

DEKRA

CONDITION REPORT


Report No:
2017315458
DATE
22/10/2026




Carpet Rear




Carpet Rear




Rear bumper



Rear Fender Left



Rear Fender Left



Door Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853


DEKRA

CONDITION REPORT


Report No:
2017315458
DATE
22/10/2026




Door Front Left



Front Fender Right



Front Fender Left



Front Bumper



Water level



Door Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853


DEKRA

CONDITION REPORT

Report No:
2017315458
DATE
22/10/2026



Door Rear Right



Rear Fender Right



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Door Sealing Rubber Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00264853