DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	15/10/2026		
Inspection Date	15/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	JF58CGGP
Model	ALMERA 1.5 ACENTA [2016-2023]	Register Number	
VIN	MDHBBAN17Z0727349	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/05/2026
Color	SILVER	Power / Displacement	
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	135,944 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Caps Missing	Replace
Water level Insufficient	Repair
Bonnet safety caps Defective	Repair
Headlight Left Damaged	Repair
Headlight Right Damaged	Repair
Front Bumper Damaged	Repair
Grill Cracked	Repair
Bonnet Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Chipmarks	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Windscreen Chipped	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Main Beam Right Dented	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Defective	Repair
Body exterior	Vehicle got minor scratches, stone chips and dents
Body exterior	Signs of spray work done on some body panels
All four tires deferred name brand	Repair
Antenna missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.0	-	
Rear	1.2	1.3	-	
Emergency / Parking	1.4	0.1	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88T	Firestone	Winter hawk	V	0516	3 mm
Front Right	185/65R15	88T	Semperit	Speed-grip	V	4410	3 mm
Rear Left	185/65R15	88H	Dunlop	Enasave	V	4122	2 mm
Rear Right	185/65R15	88Q	Goodyear	Icenav	V	3716	3 mm
Spare	165/65R15	82H	Dunlop	Sp sport	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PAST	C1601	BATTERY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026



Shock and brake report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026



ADDITIONAL 8



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



Coolant bottle


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT


Report No:
2017312883
DATE
15/10/2026



Parking Brake Performance



Caps



Water level



Bonnet safety caps



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349


DEKRA

CONDITION REPORT


Report No:
2017312883
DATE
15/10/2026



Main Beam Right



Bonnet



Windscreen



Rear bumper



Boot Lid / Hatch door



Rear Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT


Report No:
2017312883
DATE
15/10/2026



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT


Report No:
2017312883
DATE
15/10/2026



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349

DEKRA

CONDITION REPORT

Report No:
2017312883
DATE
15/10/2026



CV Joint(s) Boot(s) Front Right (inner/outer)



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0727349