DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	DATSUN	Registration Number	KF70CTGP
Model	GO 1.2 MC MID 5-DR [2018-2022]	Register Number	
VIN	MDHZBAAD0Z0513822	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	167,836 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Bonnet stay and shocks Missing	Replace
Radio/CD/USB Defective	Repair
Headlight Right Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Roof Paintwork • Flaking	Repair
Shock Absorber Rear Left Leak	Replace
Tyre Front Right Smooth	Replace
Gearbox Mountings Defective	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Engine management lights illuminated	Repair
Boot not opening can not see spare wheel	Repair
Antenna missing	Replace
All four hup caps missing	Replace
L/F fender liner missing	Replace
All four tires deferred name brand and sizes	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.9	2.0	-	
Rear	1.4	1.4	-	
Emergency / Parking	0.8	0.7	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Warrior	R699	V	2120	2 mm
Front Right	175/65R14	82H	Velocity	Rota-Eco	V	2125	0 mm
Rear Left	165/70R14	81T	Goodyear	Efficient gr	V	0622	2 mm
Rear Right	175/65R14	82T	Hankook	Optimo	V	2419	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	P0136	HEATED OXYGEN SENSOR HO2S2 BANK 1	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822


DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



RR TYRE TREAD



RF TYRE TREAD



Coolant bottle



Oil cap and dipstick



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026




CHASSIS




VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



Water level




Headlight Right




Bonnet stay and shocks



Bonnet



Front Fender Right



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



Roof



Rear Fender Right



Door Rear Right



Door Front Right



Sill Panel Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



Front Bumper



Grill



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



Shock Absorber Rear Left



Tyre Front Right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822

DEKRA

CONDITION REPORT

Report No:
2017315454
DATE
21/10/2026



CV Joint(s) Boot(s) Front Right (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox Mountings



Radio/CD/USB

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHZBAAD0Z0513822