DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	30/09/2026		
Inspection Date	29/09/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	HZ61YKGP
Model	KWID/ HATCH BACK	Register Number	
VIN	MEEBBA00100658483	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	102,227 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026





Damage	Repair Way
Engine Damaged	Repair
Air conditioner pipes Damaged	Repair
Indicator Light Front Right Damaged	Replace
Fuse box and fuses Defective	Repair
Door Handle Front Right Missing	Replace
Door Handle Rear Right Missing	Replace
Parcel Tray Missing	Replace
Window Winder rear right Missing	Replace
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Rear Axle Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Smooth	Replace
Main Beam Left Welded	Replace
Main Beam Right Welded	Repair
Engine to silencer pipe Welded	Repair
Gearbox Mountings Damaged	Repair
Gearbox Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Airbag warning lights illuminated	Repair
Signs of welding on chassis	Repair
foreign substance on oil cap	Repair
Vehicle safety integrity compromise	Repair
Body panels misaligned.	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.6	1.9	-	
Rear	1.2	1.2	-	
Emergency / Parking	0.9	0.5	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	155/80R13	79T	Ceat	Milaze	V	0619	2 mm
Front Right	155/80R13	79T	Sumitomo	HTR	V	4122	0 mm
Rear Left	155/80R13	79T	Ceat	Miaze	V	0619	3 mm
Rear Right	155/80R13	79T	Dunlop	Sport	V	3715	0 mm
Spare	155/70R13	79T	Dunlop	Sports	V	//////////	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRB	DTC800113	DRIVER FRONT AIR BAG CIRCUIT 1 OPEN CIRCUIT	
2	INJECTION	DTC065711	MAIN RELAY CONTROL CIRCUIT SHORT CIRCUIT TO 6	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of poor repair on body panels. Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483


DEKRA

CONDITION REPORT


Report No:
2017305041
DATE
29/09/2026



Shock and brake report




Diagnostics report




Diagnostics report



Diagnostics report



Diagnostics report



Diagnostics report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



90 DEGREE FRONT




90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483


DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



ENGINE 2



CHASSIS




REAR



Windscreen washer reservoir ca



Airbag warning lights illumina



Oil cap and dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483


DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



Oil cap



Coolant reservoir



Body panels misaligned.



Door Handle Rear Right



Door Handle Front Right



Indicator Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT


Report No:
2017305041
DATE
29/09/2026



Front Fender Right




Door Front Right



Door Rear Right



Window Winder rear right



Rear Fender Right



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT


Report No:
2017305041
DATE
29/09/2026



Spare Tyre




Boot Lid / Hatch door



Rear Fender Left



Front Fender Left



Fuse box and fuses



Main Beam Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026




Main Beam Left



Main Beam Right




Main Beam Right



Air conditioner pipes



Air conditioner pipes



Air conditioner pipes


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026




Engine




Engine



Tyre Front Right



Main Beam Right



Bonnet slam plate (Shock tower/ Inner tray)



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



Front Bumper



Front Bumper



Front Bumper



Control Arm Bush(es) Front Axle Left



Tyre Rear Right



Main Beam Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT


Report No:
2017305041
DATE
29/09/2026



Main Beam Left



CV Joint(s) Boot(s) Front Left (inner/outer)




Gearbox Mountings



Gearbox Mountings



Gearbox



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



Gearbox



Engine



Engine



Engine



Engine



Main Beam Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026


Main Beam Right


Engine to silencer pipe


Engine to silencer pipe


Engine to silencer pipe


Engine to silencer pipe


Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483

DEKRA

CONDITION REPORT

Report No:
2017305041
DATE
29/09/2026



Rear Axle



Rear Axle



Rear Axle



Water level



Windscreen



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100658483