DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	JM95JZGP
Model	KWID	Register Number	
VIN	MEEBBA00700715205	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2026
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	119,520 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Tyre Front Left Worn	Replace
Battery loose	Repair
Rear tyres size differs	Replace
Front tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.74	2.05	-	
Rear	1.51	1.27	-	
Emergency / Parking	0.96	0.32	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82T	Continental	Contieco	V	0721	0 mm
Front Right	175/70R13	82T	Durun	Radial	V	0125	4 mm
Rear Left	165/70R14	81T	Goodyear	Assurance	V	3523	2 mm
Rear Right	175/65R14	82T	Continental	Contieco	V	0821	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ	DTC011517	WATER TEMPERATURE SENSOR CIRCUIT VOLTAGE TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS. SIGNS OF HAIL DAMAGE TO SOME BODY PANELS. 28 DTC'S AT TIME OF TESTING SEE DTC REPORT.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



ENGINE 1



Undercarriage front.




Undercarriage rear.



Oil cap and dipstick.



Oil cap and dipstick.



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT


Report No:
2017315696
DATE
22/10/2026




RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Brake test.



Diagnostic Report page 1



Diagnostic Report page 2


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



CAN communication — Signal missing — Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC95B224	Reverse gear circuit	Memory

DAV(Variable power assist steering) (2 DTCs)

DTC	Description	Status
DTC560849	Computer Internal electronic failure	Memory
DTCD20086	Vehicle speed multiplexed information Invalid signal	Memory

Technician Notes
2017315696

Customer name:
Technician:
Date:

Diagnostic Report page 3



Water level




Front Bumper



Front Bumper



Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026




Rear Fender Left




Door Front Left




Door Rear Left



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026




Door Front Right



Door Rear Right



Rear Fender Right



Front Fender Right



Roof



Seat Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205

DEKRA

CONDITION REPORT

Report No:
2017315696
DATE
22/10/2026



Tyre Front Left



Engine



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700715205