DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	RENAULT	Registration Number	HCZ005L
Model	KWID	Register Number	
VIN	MEEBBA00900839072	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	GREEN	Power / Displacement	
Year Model		Paint Finish	PEARL EFFECT
Km Reading	69,077 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Interior Lights Defective	Repair
Indicator Light Front Left Damaged	Replace
Indicator Light Front Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Parcel Tray Missing	Replace
Boot Carpet Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
C • Pillar Right Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Damaged	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Dented	Repair
Roof Dented	Repair
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Shock Absorber Rear Right Sweat	Replace
Alignment Poor Alignment	Repair
Rear Axle Damaged	Repair
Ball Joint(s) Front Axle Right Loose / Excessive Play	Repair
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Torn / Cut	Replace
Spare Tyre Damaged	Replace
Rim Rear Left Dented	Repair
Rim Spare Wheel Dented	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Replace
Silencer Damaged	Replace
Fuel Lines Defective	Repair
Radiator Cradle Damaged	Replace
Engine Noise Excessive	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Airbag warning light illuminated on dashboard	Repair
Flywheel dust cover damaged	Replace
Engine cover damaged	Replace
Rear left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No: 2017314864
DATE 21/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	1.87	-	
Rear	1.13	0.53	-	
Emergency / Parking	0.84	0.52	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Ceat	Fuelsmart	V	0723	1 mm
Front Right	165/70 R14	81R	Ceat	Temporary	V	0823	0 mm
Rear Left	185/60 R14	82H	Dunlop	Sp-Sport	V	0521	0 mm
Rear Right	165/70 R14	81T	Ceat	Fuelsmart	V	0723	4 mm
Spare	175/65 R14	82H	Firestone	Touring	V		0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC011517	WATER TEMPERATURE SENSOR CIRCUIT TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Signs of impact damage to front of vehicle.Dents and scratches on body panelsBody panels misaligned.
Axle and Suspension: Front suspension faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



90 DEGREE RIGHT



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Rear chassis



Front chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Oil cap and dipstick



Spare wheel and Accessories




ENGINE COVER



ENGINE 1



Flywheel dust cover



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



LR TYRE TREAD



RR TYRE TREAD




RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



Diagnostic report page 3

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072


DEKRA

CONDITION REPORT


Report No:
2017314864
DATE
21/10/2026



Diagnostic report page 2



Diagnostic report page 1



Brake and shock absorber repor



Hood Lining



Steering Wheel Trim



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Door Sealing Rubber Front Right




C • Pillar Right



Seat Rear



Door Rear Right



Front Fender Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Front Fender Left



Door Front Left




Door Rear Left



Rear Fender Left



Rim Rear Left



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Door Sealing Rubber Rear Left



Rear bumper



Boot Lid / Hatch Door Rubbers



Boot Carpet



Parcel Tray



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Spare Tyre




Rim Spare Wheel



Indicator Light Front Right



Indicator Light Front Left



Brake test

Brake force

	left	right	Difference
Front axle	2,20 kN	1,87 kN	15 %
Parking brake	0,84 kN	0,52 kN	38 %
Rear axle	1,13 kN	0,53 kN	53 %
Final evaluation static			
Deceleration service brake		78 %	
Deceleration parking brake		18 %	Total weight 749 kg

Service Brake Performance Rear Axle



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Front Fender Right / Inner Tray



Tyre Rear Right



Rear bumper



Sill Panel Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Front Bumper



Engine



Sub Frame



Sub Frame



Chassis



Chassis


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Silencer



Fuel Lines




Rear Axle



Inner Boot Floor Pan and Spare Wheel Well



Tyre Rear Left



Shock Absorber Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072


DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Tyre Front Right



Tyre Front Left



Radiator Cradle



Ball Joint(s) Front Axle Right



Indicator Light Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072

DEKRA

CONDITION REPORT

Report No:
2017314864
DATE
21/10/2026



Water level



Interior Lights



Side Mirror Left



Roof



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900839072