



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	21/09/2026		M57 Pretoria Road - 1619
Inspection Date	21/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	LS03YCGP
Model	KIGER	Register Number	
VIN	MEEHBC00100089995	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	171,383 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Hoses Oil Leak	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Central Locking Malfunction	Replace
Tail Light Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Door Panel Front Left Damaged	Repair
Door Panel Rear Left Damaged	Repair
Door Panel Rear Right Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Gear Lever Dust Boot Damaged	Repair
Steering Wheel Trim Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Left Damaged	Repair
C • Pillar Right Damaged	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Defective	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Fuel Cap Damaged	Repair
Windscreen Cracked	Replace
Shock Absorber Front Left Sweat	Replace
Shock Absorber Rear Left Leak	Replace
Shock Absorber Rear Right Leak	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Worn	Replace
Main Beam Left Damaged	Repair
Main Beam Right Damaged	Repair
Chassis Dented	Repair
Engine to silencer pipe Damaged	Repair
Silencer Damaged	Replace
Gearbox Oil Sweat	Repair
Fuel Tank Damaged	Replace
Warning light illuminated on dashboard	Repair
Rear right inner sill panel plastic trim damaged	Replace

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.15	2.72	-	
Rear	1.96	1.9	-	
Emergency / Parking	1.04	0.91	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60 R16	89V	Ceat	Secure drive	V	2122	2 mm
Front Right	195/60 R16	89V	Ceat	Secure drive	V	2122	2 mm
Rear Left	195/60 R16	89H	Nexen	Nblue	V	2722	0 mm
Rear Right	195/60 R16	89V	Ceat	Secure drive	V	0623	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC256200	BOOST PRESSURE SENSOR GENERAL ELECTRICAL FAILURE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Boot does not open. Dents and scratches on body panels. Signs of impact damage to rear of vehicle. Body panels misaligned. Vehicle safety integrity compromised. Poor residual traces of repair on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026

VEHICLE INFORMATION			
Make/Model	Year	Registration	Color
Renault Kwid	2017	2017301672	White
Engine No.	Chassis No.	Vehicle No.	Inspection Date
10000000000000000000	10000000000000000000	10000000000000000000	21/09/2026
BRAKE AND SHOCK ABSORBER INSPECTION			
Component	Inspection Details	Findings	Remarks
Front Brake	Discs: 2mm thickness, Pads: 1mm thickness	Wear on pads, disc surface smooth	OK
Rear Brake	Discs: 3mm thickness, Pads: 2mm thickness	Wear on pads, disc surface smooth	OK
Shock Absorbers	Left: 100% function, Right: 100% function	No leaks, no noise	OK
Steering	Alignment: 0% deviation	Steering wheel straight	OK
Wheels/Tyres	Pressure: 2.0 bar, Tread: 5mm	No damage, good tread	OK
Overall Condition	PASS		

Brake and shock absorber report

Renault Kwid Diagnostic Report	
Engine	1000cc, 10000000000000000000
Transmission	5-Speed Manual
Brake System	Disc/Pad, 10000000000000000000
Shock Absorbers	10000000000000000000
Steering	10000000000000000000
Wheels/Tyres	10000000000000000000
Lighting	10000000000000000000
Electrical	10000000000000000000
Exhaust	10000000000000000000
Overall Condition	PASS

Diagnostic report page 1

Renault Kwid Diagnostic Report	
Engine	1000cc, 10000000000000000000
Transmission	5-Speed Manual
Brake System	Disc/Pad, 10000000000000000000
Shock Absorbers	10000000000000000000
Steering	10000000000000000000
Wheels/Tyres	10000000000000000000
Lighting	10000000000000000000
Electrical	10000000000000000000
Exhaust	10000000000000000000
Overall Condition	PASS

Diagnostic report page 2

Renault Kwid Diagnostic Report	
Engine	1000cc, 10000000000000000000
Transmission	5-Speed Manual
Brake System	Disc/Pad, 10000000000000000000
Shock Absorbers	10000000000000000000
Steering	10000000000000000000
Wheels/Tyres	10000000000000000000
Lighting	10000000000000000000
Electrical	10000000000000000000
Exhaust	10000000000000000000
Overall Condition	PASS

Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Rear right inner sill panel pl



Engine Wiring



Water level



Hoses



Gear Lever Dust Boot



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Center Console / Cubbyhole + Lid



Hood Lining



Rear Fender Right



Door Rear Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Front Fender Right



Front Fender Right



Windscreen



Tail Light Right



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Rear Fender Left



Door Rear Left



Door Rear Left



Door Front Left



Door Front Left



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Bonnet



Seat Front Right



Door Sealing Rubber Front Right



Central Locking



Seat Rear



Door Panel Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE


21/09/2026



C • Pillar Right



C • Pillar Left



Seat Rear



Door Panel Rear Left



Seat Front Left



Door Panel Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026



Control Arm Bush(es) Front Axle Right



Rear Fender Right / Inner Tray



Inner Boot Floor Pan and Spare Wheel Well



Shock Absorber Rear Left



Shock Absorber Rear Right



Rear Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Shock Absorber Front Left



Control Arm Bush(es) Front Axle Left



Engine



Engine to silencer pipe



Gearbox



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Chassis



Fuel Tank



Fuel Tank



Tyre Rear Left



Main Beam Left



Main Beam Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995



CONDITION REPORT



Report No:

2017301672

DATE

21/09/2026



Main Beam Right



Main Beam Right



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Silencer



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEHBC00100089995



CONDITION REPORT



Report No:
2017301672
DATE
21/09/2026



Fuel Cap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00100089995