DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	07/10/2026		
Inspection Date	07/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	KR58XZGP
Model	KIGER	Register Number	
VIN	MEEHBC00700054801	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	178,938 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



Damage	Repair Way
Center Console / Cubbyhole + Lid Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
A • Pillar Right Defective	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Shock Absorber Rear Left Leak	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Gearbox Oil Leak	Repair
Three hub caps were missing	Replace
The right front fender liner was damaged	Replace
Brake test failed	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.26	2.47	-	
Rear	1.41	1.82	-	
Emergency / Parking	0.89	1.09	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	87V	Apollo	Alnac	V	4923	3 mm
Front Right	195/55R16	87V	Apollo	Alnac	V	5024	3 mm
Rear Left	185/55R16	83H	Bridgestone	Ecopia	V	1325	3 mm
Rear Right	195/55R16	91V	Royal black	Royal mile	V	3324	3 mm
Spare	185/65R15	88R	Ceat	Stepnee	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC001177	INLET CAMSHAFT SHIFTER COMMAND IMPOSSIBLE	MEMORY

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



REAR LEFT CORNER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



MANUAL GEAR LEVER



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



LR TYRE TREAD



RR TYRE TREAD



ENGINE 1



ENGINE 2



CHASSIS



OIL CAP AND DIPSTICK

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026




COOLANT EXPANSION BOTTLE




SPARE WHEEL




LICENSE DISC



VIN PLATE OR STICKER



SHOCK AND BRAKE TEST REPORT



DIAGNOSTIC REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT


Report No:
2017308422
DATE
07/10/2026



DIAGNOSTIC REPORT



DIAGNOSTIC REPORT



DIAGNOSTIC REPORT



Water level



Center Console / Cubbyhole + Lid



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



Rear bumper



Rear bumper



A • Pillar Right



Bonnet



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



Door Front Right




Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801

DEKRA

CONDITION REPORT

Report No:
2017308422
DATE
07/10/2026



Door Rear Left



Rear Fender Left



Shock Absorber Rear Left



Gearbox



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00700054801