DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	JXB158MP
Model	AVANZA	Register Number	
VIN	MHKM5EA1N0K002888	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2025
Color	GOLDEN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	260,172 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Replace
Seat Rear (2. Row) Damaged	Repair
Steering Wheel Trim Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Brake disc 1. Axle left Damaged	Replace
Brake disc 1. Axle right Damaged	Replace
Parking Brake Performance Insufficient	Repair
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Mounting Rubber(s) Rear Axle Left Worn	Replace
Mounting Rubber(s) Rear Axle Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Gearbox Oil Leak	Repair
Engine Performance Insufficient	Repair
Engine Noise Excessive	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	**Braking Force [KN]**	**Axle Weight [KG]**	**Deceleration [m/s²]**
Front	1.91	2.4	-	
Rear	0.42	0.64	-	
Emergency / Parking	0	0	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	88H	Vanza	Radio	V	4323	0 mm
Front Right	175/65R14	82T	Velocity	Radial	V	4816	0 mm
Rear Left	185/60R14	82H	Sava	Radial	V	0316	0 mm
Rear Right	175/65R14	82T	Continental	Contieco	V	3215	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	EFI	P0014	EXHAUST DUAL VARIABLE VALVE TIMING ADVANCE FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 22 DTC'S AT TIME OF TESTING SEE DTC REPORT.Engine Compartment: Battery loose. Oil cap and dipstick.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition.
Brakes: handbrake does not work.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026




90 DEGREE RIGHT




DASHBOARD (W/ ENGINE RUNNING)




Manual.



Brake test.



Diagnostic.



Diagnostic.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



ODOMETER



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



Bonnet slam plate (Shock tower/ Inner tray)



Front Bumper




Front Bumper



Bonnet



Front Fender Left



Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT


Report No:
2017317764
DATE
27/10/2026



Door Front Left




Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



Door Rear Right



Door Front Right




Rear Fender Right



Seat Front Right



Seat Rear



Seat Rear (2. Row)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT


Report No:
2017317764
DATE
27/10/2026



Seat Rear




Seat Front Left



Tail Light Left



Tail Light Right



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT


Report No:
2017317764
DATE
27/10/2026



Tyre Rear Left




Tyre Front Left




Tyre Front Right



Engine



Gearbox



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888


DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



Control Arm Bush(es) Front Axle Right




Mounting Rubber(s) Rear Axle Left




Mounting Rubber(s) Rear Axle Left



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Right



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888

DEKRA

CONDITION REPORT

Report No:
2017317764
DATE
27/10/2026



Brake disc 1. Axle left



Brake disc 1. Axle right



Engine Management Lights



Steering Wheel Trim



Central Air Vent



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5EA1N0K002888