DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	07/09/2026		
Inspection Date	07/09/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	JJT076NW
Model	SANDERO II 0.9 STEPWAY 66KW TURBO 5-DR [2014-2017]	Register Number	
		Date Of First Licensing	
VIN	VF15SRAAC51695230	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	BLUE	Paint Finish	TWO COAT UNI
Year Model	2014	Fuel	PETROL
Km Reading	244,023 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026





Damage	Repair Way
Engine Oil Leak	Repair
Under bonnet insulation cover Damaged	Repair
Hooter Defective	Repair
Indicator Light Front Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Defective	Repair
Seat Front Right Defective	Repair
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Door Panel Front Right Damaged	Repair
Door Panel Rear Left Damaged	Repair
Door Panel Rear Right Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Door Lock Front Left Damaged	Replace
Parcel Tray Damaged	Repair
Brake Pedal Rubber Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Right Paintwork • Chipmarks	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Damaged	Repair
Stabilizer Mounting Front Right Damaged	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Right Worn	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Rim Rear Left Damaged	Repair
Belly plates Damaged	Replace
Engine Noise Excessive	Repair
Engine Smoke Excessive	Repair
Clutch Operation Shudder	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Vehicle license disk missing	Replace
Gear knob damaged	Replace
Rear left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No: 2017295259
DATE 07/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.95	2.67	-	
Rear	2.16	2.05	-	
Emergency / Parking	0.98	1.19	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91W	Velocity	Speedmax	V	3322	2 mm
Front Right	205/55R16	94V	Davanti	DX390	V	4221	0 mm
Rear Left	205/60R16	92H	Westlake	Radial	V	3621	1 mm
Rear Right	205/55R16	91V	Sumitomo	BC100	V	2319	1 mm
Spare	205/55R16	91V	Sumitomo	BC100	V	5018	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC010516	INLET MANIFOLD PRESSURE SENSOR CIRCUIT SIGNAL OUTS	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.Engine Compartment: Traces of repair work done on engine oil sump.
Electrical Components and Instruments: Vehicle hooter not working.
Lights: Front right headlight lens faded.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Dents and scratches on body panels
Brakes: Rear right handbrake cable loose.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Brake and shock absorber repor



Front chassis



Rear chassis



Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Spare Wheel



Oil cap and dipstick



Manual Transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT


Report No:
2017295259
DATE
07/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



ENGINE 1



Steering Wheel Trim



Hood Lining



Door Sealing Rubber Front Right



Seat Front Right



Door Panel Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Door Panel Rear Right



Seat Rear



Rear Fender Right



Rear Fender Right



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Door Front Right


Door Front Right


Front Fender Right


Side Mirror Right


Indicator Light Front Right


Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Rear bumper



Rear bumper


Roof


Rear Fender Left


Door Rear Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Door Front Left



Seat Rear



Sill Panel Left



Door Panel Rear Left



Door Panel Rear Left



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Headlight Right



Brake Pedal Rubber



Hooter



Spare Tyre



Spare Tyre



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Water level



Under bonnet insulation cover



Front Bumper



Front Bumper



Front Bumper



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Tyre Front Right



Rim Front Left



Engine



Stabilizer Mounting Front Right



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230

DEKRA

CONDITION REPORT

Report No:
2017295259
DATE
07/09/2026



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Water level



Door Lock Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC51695230