DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	AUDI	Registration Number	DF02VMGP
Model	A5 COUPE 2.0 TDI DSL SE MULTITRONIC [2012-2014]	Register Number	
		Date Of First Licensing	
VIN	WAUZZZ8T8EA029017	Last COR	
Engine Number		License Expiry Date	31/07/2027
Doors	2	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT UNI
Year Model	2014	Fuel	DIESEL
Km Reading	232,435 KM	Transmission	AUTOMATIC
Cab / Body Type	COUPE		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026





Damage	Repair Way
Bonnet stay and shocks Damaged	Replace
Sun Visor Right Loose / Excessive Play	Repair
Boot Carpet Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Flaking	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Shock Absorber Front Left Sweat	Replace
Shock Absorber Front Right Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Chassis Damaged	Repair
Belly plates Damaged	Replace
Gearbox Noise Excessive	Repair
Wheel Spanner Missing	Replace
Gearbox cross member bracket damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.92	3.77	-	
Rear	2.6	3.09	-	
Emergency / Parking	1.92	2.2	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/35Z R19	96H	Sailun	Atrezzo	V	4525	5 mm
Front Right	255/35Z R19	96W	Sailun	Atrezzo	V	4525	5 mm
Rear Left	255/35Z R19	96Y	Continental	Contisport	V	2325	0 mm
Rear Right	255/35Z R19	96Y	Continental	Contisport	V	0723	0 mm
Spare	T125/70 R19	100M	Hankook	Temporary	V	2018	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	U041700	INVALID DATA RECEIVED FROM PARK BRAKE CONTROL UNIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



Oil cap



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Front chassis



Rear chassis




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017


DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Spare wheel



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



Gearbox cross member



Spare wheel Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



LICENSE DISC



VIN PLATE OR STICKER


Sun Visor Right


Rear Fender Right


Door Front Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Side Mirror Right



Rim Front Right



Windscreen



Front Fender Left



Rim Front Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Door Front Left



Rear bumper



Rear bumper



Rear bumper



Spare Tyre



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Oil level



Bonnet



Bonnet



Grill



Boot Lid / Hatch door



Boot Lid / Hatch door


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Water level



Bolt(s) / Nut(s) Front Wheel Right



Control Arm Bush(es) Front Axle Right



Shock Absorber Front Right



Shock Absorber Front Left



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Bolt(s) / Nut(s) Front Wheel Left



Front Bumper



Front Bumper



Front Bumper



Rear Fender Left / Inner Tray



Bolt(s) / Nut(s) Rear Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Bolt(s) / Nut(s) Rear Wheel Right



Rim Rear Right



Belly plates



Chassis



Chassis



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026


Control Arm Bush(es) Front Axle Right


Chassis


Tyre Rear Right


Tyre Rear Left


Shock Absorber Rear Right


Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017

DEKRA

CONDITION REPORT

Report No:
2017317497
DATE
26/10/2026



Water level



Bonnet stay and shocks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8T8EA029017