CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	30/09/2026		
Inspection Date	30/09/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	BMW	Registration Number	FR27CRGP
Model	228I COUPE SPORT LINE 8-SP AT [2014-2016]	Register Number	
VIN	WBA1F52050VZ36502	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/06/2026
Color	WHITE	Power / Displacement	
Year Model	2016	Paint Finish	C - COMMON
Km Reading	216,226 KM	Fuel	PETROL
Cab / Body Type	COUPE	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Damage	Repair Way
Engine Oil Leak	Repair
Headlight Right Damaged	Replace
Seat Front Right Torn / Cut	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Front Left Leak	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Gearbox Oil Leak	Repair
All four tires deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.0	3.3	-	
Rear	3.1	3.1	-	
Emergency / Parking	2.1	0.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R18	92Y	Michelin	Pilot sport	V	1516	3 mm
Front Right	225/40R18	88W	Win run	R330	V	0822	2 mm
Rear Left	225/40R18	92Y	Bridgestone	Potenza	V	4925	3 mm
Rear Right	225/40R18	88Y	Continental	Contact	V	1922	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	REM	804872	BRAKE LIGHT, LEFT, FAULTY	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Shock and brake report



Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



RR TYRE TREAD



RF TYRE TREAD



No spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



ENGINE 2




CHASSIS



Oil cap



Expention bottle



Test results VIN: WBA1F

side-slip test

Front axle + 2 m/km Rear axle - 6 m/km

Shock absorber test (MSD3000)

	left	right	Difference	Weight
Front axle	0,11	0,04	64 %	997 kg
Rear axle	> 0,30	0,27	10 %	938 kg
Total weight				1935 kg

Brake test

	Brake force left	right	Difference
Front axle	3,02 kN	3,36 kN	10 %
Parking brake	2,12 kN	0,69 kN	67 %
Rear axle	3,18 kN	3,14 kN	1 %
Final evaluation static			
Deceleration service brake		67 %	
Deceleration parking brake		15 %	Total weight 1935 kg

Parking Brake Performance



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Headlight Right



Front Fender Right



Rear Fender Right



Door Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Door Front Left




Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Engine



Gearbox




Gearbox



Shock Absorber Front Left



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502

DEKRA

CONDITION REPORT

Report No:
2017305420
DATE
30/09/2026



Seat Front Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA1F52050VZ36502