DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	BMW	Registration Number	JTS498NW
Model	320I AT [2008-2013]	Register Number	
VIN	WBAPG56010NN55392	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/08/2025
Color	BLUE	Power / Displacement	
Year Model	2011	Paint Finish	TWO COAT METALLIC
Km Reading	274,896 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Caps Defective	Repair
Expansion Bottle Damaged	Replace
Head Light Switch Missing	Replace
Switch Electrical Window Winder front left Malfunction	Replace
Air Conditioner Insufficient	Replace
Indicator Light Front Right Malfunction	Repair
Tail Light Left Damaged	Replace
Tail Light Right Cracked	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Belt Front Right Damaged	Replace
Hood Lining Defective	Repair
Door Handle Front Left Damaged	Replace
Door Handle Rear Left Damaged	Replace
Door Handle Rear Right Damaged	Replace
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Door Lock Front Right Missing	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Replace
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Damaged	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle right Defective	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Chassis Damaged	Repair
Engine to silencer pipe Defective	Repair
Catalytic converter Welded	Replace
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Engine Performance Insufficient	Repair
Engine Noise Excessive	Repair
Gear Selections Slippy Hesitation	Repair
Boot release switch missing	Replace
Driver's sill panel plastic trim missing	Replace
Gearbox sump dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026

Damage	Repair Way
Rear bumper stiffener damaged	Repair
ECU loose	Repair
Foreign substance on water cap	Repair
Rear tyres size differs	Replace
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.0	3.24	-	
Rear	2.62	2.62	-	
Emergency / Parking	1.19	1.19	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55 R16	91V	Dunlop	Sport	V	4824	4 mm
Front Right	205/55 R16	91V	Dunlop	Sport	V	4824	4 mm
Rear Left	205/55 R16	91V	Dunlop	Sp-Sport	V	3219	0 mm
Rear Right	205/55Z R17	94W	Triangle	Talon	V	3706	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DME(ENGINE-DIGITAL MOTOR ELECTRONICS)	00283D	DIGITAL MOTOR ELECTRONICS(DME),VANOS(VARIABLE CAMS	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Lights: Front left and right headlight lenses faded.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No: 2017316488
DATE 23/10/2026

panels.
Undercarriage: Exhaust loose.Engine splash plate missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392


DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Brake and shock absorber repor




Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3



Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026




90 DEGREE RIGHT



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



ECU




Gear box sump




Rear bumper stiffener



Oil cap



Seat Belt Front Right



Door Sealing Rubber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Door Sealing Rubber Rear Right



Rear Fender Right



Door Rear Right



Door Front Right



Side Mirror Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Front Fender Right



Side Mirror Left



Rear Fender Left



Door Sealing Rubber Rear Left



Door Handle Rear Left



Door Handle Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Door Handle Front Left



Door Sealing Rubber Front Left



Switch Electrical Window Winder front left



Expansion Bottle



Air Conditioner



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Steering Wheel Trim



Head Light Switch



Tail Light Right



Tail Light Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



Roof



Door Rear Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Door Front Left



Door Front Left




Front Fender Left



Bonnet



Indicator Light Front Right



Brake disc 1. Axle right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026




Rear Fender Left / Inner Tray



Sill Panel Left



Sill Panel Left



Front Fender Left / Inner Tray



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Front Bumper



Headlight Left



Headlight Right



Engine



Catalytic converter



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Engine Wiring




Belly plates



Chassis



Tyre Rear Right



Tyre Rear Left



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Rear Fender Left / Inner Tray



Engine to silencer pipe



Engine to silencer pipe



Engine to silencer pipe



Belly plates



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392

DEKRA

CONDITION REPORT

Report No:
2017316488
DATE
23/10/2026



Door Handle Front Left



Oil level



Caps



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAPG56010NN55392