DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MERCEDES-BENZ	Registration Number	HV99DMGP
Model	C180	Register Number	
VIN	WDD2050402R460849	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	297,255 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Hoses Water Leak	Replace
Bonnet stay and shocks Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Door Panel Front Right Cracked	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Residual Traces of Repair	Replace
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Rocker Panel Left Residual Traces of Repair	Repair
Rocker Panel Right Residual Traces of Repair	Repair
Shock Absorber Front Right Sweat	Replace
Tyre Front Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Front left panic handle loose	Repair
Warning light illuminated on dashboard	Repair
Front left shock absorber weak	Replace
December parking brake defective	Repair
Front bumper stiffener damaged	Repair
Front L/R chassis leg extensions damaged	Replace
Front emblem cracked	Replace
Rear right tyre regrooved	Release
Rear prop shaft vibration rubber cracked	Replace
Spare wheel missing	Replace
Aircon condenser dented	Repair
Parking sensor switch malfunction	Replace
Front left inner A pillar plastic trim loose	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No: 2017316010
DATE 22/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.23	3.5	-	
Rear	2.21	2.11	-	
Emergency / Parking	0.63	0.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/50 R17	94W	Goodyear	Efficient	V	3421	0 mm
Front Right	225/50Z R17	98W	Sunwide	RS-one	V	1520	2 mm
Rear Left	215/45 R17	91W	Hankook	Ventus	V	3316	3 mm
Rear Right	225/45 R17	91Y	Dunlop	Sport	V	2813	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	TCM(TRANSMISSION CONTROL UNIT)	P073E00	REVERSE GEAR CANNOT BE ENGAGED	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Vehicle electronics malfunction.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front and rear of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026




LR TYRE TREAD



LF TYRE TREAD



Front chassis



Rear chassis



VIN PLATE OR STICKER



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



DIAGNOSTIC REPORT PAGE 1




DIAGNOSTIC REPORT PAGE 2




DIAGNOSTIC REPORT PAGE 3



DIAGNOSTIC REPORT PAGE 4



DIAGNOSTIC REPORT PAGE 5



SHOCK AND BRAKE REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Front bumper stiffener



Oil cap and dipstick



Front left panic handle



Triangle



Front left chassis leg extensi



Front right chassis leg extens

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Front emblem



Rear prop shaft vibration rubb



Aircon condenser



Parking sensor switch



Front left inner A pillar plas



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026




Center Console / Cubbyhole + Lid



Door Panel Front Right



Seat Front Right



Seat Rear



Seat Rear



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Rim Front Left



Windscreen Wiper



Rim Front Right



Front Fender Right



Door Front Right



Door Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Door Rear Right



Rear Fender Right




Rim Rear Right



Front Fender Left



Door Front Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Boot Lid / Hatch door



Rear bumper


Rear bumper


Rear bumper



Tail Light Left


Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT


Report No:
2017316010
DATE
22/10/2026



Boot Lid / Hatch Door Rubbers



Bonnet stay and shocks



Bonnet stay and shocks



Headlight Left



Headlight Right



Bonnet slam plate (Shock tower/ Inner tray)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Front Fender Right / Inner Tray



Front Bumper



Front Bumper



Front Bumper



Grill



Rocker Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Rocker Panel Right



Tyre Front Left



Shock Absorber Front Right



Gearbox



Gearbox



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Belly plates



Engine to silencer pipe



Tyre Rear Right



Belly plates



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Rear Fender Right / Inner Tray



Belly plates



Door Rear Left



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849

DEKRA

CONDITION REPORT

Report No:
2017316010
DATE
22/10/2026



Water level



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R460849