DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	PORSCHE	Registration Number	CW05PCGP
Model	CAYENNE E2 S 4.8 V8 4X4 8-SP TIPTRONIC [2010-2014]	Register Number	
		Date Of First Licensing	
VIN	WP1ZZZ92ZELA56725	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2013	Fuel	PETROL
Km Reading	154,831 KM	Transmission	AUTOMATIC
Cab / Body Type	SUV		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Management Lights Set	Repair
Switch Electrical Window Winder front left Defective	Repair
Switch Electrical Window Winder front right Defective	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Dented	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Steering box Leak	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Right Worn	Replace
Spare Tyre Defective	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
4x4 Differential Lock Malfunction	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/55R18	109V	Michelin	Radial	V	1116	0 mm
Front Right	255/55R18	109W	Hilo	Radial	V	4620	0 mm
Rear Left	255/55R18	109W	Hilo	Radial	V	4620	2 mm
Rear Right	255/55R18	109W	Hilo	Radial	V	4620	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DME	P1572	CONTROL UNIT RUN ON NOT ENDED CORRECTLY	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 32 DTC'S AT TIME OF TESTING SEE DTC REPORT.Electrical Components and Instruments: vehicle electronics malfunctioning. automatic opening hatchdoor malfunctioning. hatchdoor does not open or close properly.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.
Tyres and Rims: Spare wheel missing.
Undercarriage: signs of surfaced rust on undercarriage of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap.



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026




Undercarriage front.




Undercarriage rear.



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT


Report No:
2017315344
DATE
22/10/2026



NO LICENSE DISC




VIN PLATE OR STICKER



Brake test.



Diagnostic.



Diagnostic.



Diagnostic.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725


DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



Door Front Right



Front Fender Right



Bolt(s) / Nut(s) Rear Wheel Left



Tyre Front Left



Tyre Front Right



Engine


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



Gearbox



Belly plates



Steering box



Tyre Rear Right



Switch Electrical Window Winder front left



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725

DEKRA

CONDITION REPORT

Report No:
2017315344
DATE
22/10/2026



Engine Management Lights



4x4 Differential Lock



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WP1ZZZ92ZELA56725