DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	HM99RPGP
Model	KOMBI T6 SWB 2.0 TDI TRENDLINE MPV DSL 75KW [2016-2018]	Register Number	
		Date Of First Licensing	
VIN	WV2ZZZ7HZHH098875	Last COR	
Engine Number		License Expiry Date	30/11/2025
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2017	Fuel	DIESEL
Km Reading	384,440 KM	Transmission	MANUAL
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Switch Electrical Window Winder front left Damaged	Replace
Switch Electrical Window Winder front right Damaged	Replace
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Shock Absorber Rear Right Worn	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Repair
Spare Tyre Damaged	Replace
Engine mountings Damaged	Replace
Excessive noise from front and rear suspension.	Repair
Rear tyres size differs	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No: 2017316738
DATE 23/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.94	3.94	-	
Rear	2.93	3.2	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205R16C	108S	Continental	Worldcontac	V	3220	0 mm
Front Right	205R16C	108S	Continental	Worldcontac	V	0324	0 mm
Rear Left	215/70R16	106T	Goodyear	Marathon	V	0424	0 mm
Rear Right	215/65R16	98H	General	Radial	V	3816	0 mm
Spare	195/75R16	108R	Dunlop	Sp	V	1022	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODEL 1	P023600	TURBOCHARGER ROOST SENSOR CIRCUIT RANGE PERFORMANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose.
Electrical Components and Instruments: driver side electric window does not close.
Body • Exterior: Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition. Repair work done to vehicle below standard.
Tyres and Rims: Spare tire does not hold pressure.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875


DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026




Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT


Report No:
2017316738
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Water level




Headlight Right



Headlight Left



Tail Light Left



Windscreen Wiper



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875


DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Front Bumper



Front Bumper




Bonnet



Grill



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026




Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Door Front Right



Rear Fender Right



Front Fender Right



Side Mirror Right



Side Mirror Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026




Windscreen




Side Mirror Left




Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875


DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Engine



Engine mountings



Shock Absorber Rear Right



Spare Tyre


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Seat Front Right



Seat Front Left



Seat Rear



Seat Rear (2. Row)



Engine Management Lights



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875

DEKRA

CONDITION REPORT

Report No:
2017316738
DATE
23/10/2026



Central Air Vent



Switch Electrical Window Winder front left



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV2ZZZ7HZHH098875