DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	19/10/2026		
Inspection Date	19/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	JD92NDGP
Model	GOLF 7 2.0 TSI GTI 5-DR DSG [2019-2021]	Register Number	
VIN	WVWZZZAUZKW103130	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT UNI
Km Reading	206,898 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Caps Missing	Replace
Hoses Oil Leak	Replace
Fan Belt Damaged	Replace
Bonnet stay and shocks Damaged	Replace
Under bonnet insulation cover Damaged	Replace
Fog Light Front Right Damaged	Replace
Seat Front Right Damaged	Repair
Seat Belt Front Right Damaged	Replace
Parcel Tray Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Windscreen Chipped	Repair
Brake fluid level Insufficient	Replace
Shock Absorber Rear Left Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Tyre Rear Left Torn / Cut	Replace
Tyre Rear Right Damaged	Replace
Rim Rear Left Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Engine to silencer pipe Welded	Replace
Silencer Missing	Replace
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Fuel Tank Sweat	Repair
CV Joint(s) Front Left (inner/outer) Loose / Excessive Play	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Brakes Malfunction	Repair
Engine Noise Excessive	Repair
Warning lights illuminated on dashboard	Repair
Signs of vehicle overheating	Repair
Loose wiring inside boot of vehicle	Repair
Front bumper stiffener damaged	Replace
Front right headlight washer pipe damaged	Replace
Rear right tyre regrooved	Replace
Windscreen washer bottle cap missing	Replace
Driver's foot rest pedal missing	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No: 2017313846
DATE 19/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.52	3.93	-	
Rear	2.5	2.52	-	
Emergency / Parking	1.52	1.53	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40Z R18	92Y	Sumitomo	HTR	V	2022	1 mm
Front Right	225/40Z R18	92Y	Sumitomo	HTR	V	3323	1 mm
Rear Left	225/40Z R18	92Y	Sumitomo	HTR	V	3323	1 mm
Rear Right	225/40Z R18	92W	Saffiro	SF5000	V	1018	0 mm
Spare	T125/70 R18	99M	Linglong	Temporary	V	4218	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P006800	MAP/MAF-THOTTLE POSITION,CORRELATION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT AND REAR OF VEHICLE / ENGINE SPLASH PLATE MISSING.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



ENGINE 1



Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026




RR TYRE TREAD



LR TYRE TREAD



Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Loose wiring



Front bumper stiffener



Front right headlight washer p



Tyre Rear Left



Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Bolt(s) / Nut(s) Front Wheel Right



Windscreen



Seat Belt Front Right



Seat Front Right



Seat Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Door Front Right



Door Rear Right



Door Rear Right



Rear Fender Right



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Rear bumper



Rear Fender Left



Door Rear Left



Door Front Left



Door Front Left



C • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Parcel Tray



Bonnet stay and shocks



Under bonnet insulation cover



Water level



Fan Belt



Brake fluid level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Caps




Sill Panel Right



Front Bumper



Front Bumper



Sill Panel Left



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Silencer



Silencer



Gearbox



Engine



Engine Wiring



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



CV Joint(s) Front Left (inner/outer)



Hoses



Fog Light Front Right



Belly plates



Belly plates



Fuel Tank

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Silencer



Tyre Rear Right




Shock Absorber Rear Left



Shock Absorber Rear Right



Engine to silencer pipe



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130

DEKRA

CONDITION REPORT

Report No:
2017313846
DATE
19/10/2026



Engine Wiring



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZAUZKW103130