

JEEP VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/JEEP/WK-Grand cherokee/--
 VIN: 1C4RJFGM0FC829321

Odometer Reading: 209968
 License Plate: FP96TBGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572


















Device information

Scanner: MaxiSys MS906 BT
 Version: V10.60

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned(31)

| System | Status/DTC |
|--------------------------------------|------------|
| ECM(Engine Control Module) | 5 |
| TCM(Transmission Control Module) | 0 |
| DTCM(Drive Train Control Module) | 0 |
| ABS(Anti Lock Brakes) | 2 |
| ORC(Air Bag/Occupant Restraint) | 1 |
| IPC(Instrument Panel Cluster) | 2 |
| TPM(Tire Pressure Monitor) | 5 |
| BCM(Body Controller) | 1 |
| RADIO(Radio) | 2 |
| HVAC(Heat, Ventilation And A/C) | 0 |
| EPS(Electric Power Steering) | 1 |
| AFLS(Adaptive Front Lighting System) | 4 |
| PDM(Passenger Door Module) | 3 |
| ITM(Intrusion Transceiver Module) | 2 |
| SCCM(Steering Column Control Module) | 2 |
| AMP(Amplifier) | 0 |
| PTS(Parktronics) | 2 |
| ICS(Integrated Center Stack) | 0 |

| | | |
|--|---|---|
| DDM(Driver Door Module) | |  3 |
| HSM(Heated Seat Module) | |  1 |
| RFH(Radio Frequency Hub) | |  5 |
| ESM(Electronic Shifter) | |  5 |
| EDM(External Disc Module) | |  1 |
| ACC(Adaptive Cruise Control) |  |  1 |
| MSM(Memory Seat/Memory Heated Seat) | |  2 |
| PLGM(Power Liftgate Module) | |  8 |
| RBSS(Right Blind Spot Sensor) |  |  1 |
| LBSS(Left Blind Spot Sensor) |  |  1 |
| FFCM(Forward Facing Camera Module) |  |  1 |
| ASCM(Air Suspension Control Module) | |  6 |
| ELSD(Electronic Limited Slip Differential) | |  0 |

DTC (67)

ECM(Engine Control Module) (5 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| P201D-00 | Intake manifold runner control actuator internal performance - bank 1 | Active |
| P0562-00 | System voltage low | Stored |
| P1E0C-00 | Empty fuel tank | Stored |
| P068A-00 | PCM power de-energized performance - too early | Stored |
| P0513-00 | Invalid SKIM key | Stored |

ABS(Anti Lock Brakes) (2 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| C2100-16 | Battery voltage low - circuit voltage below threshold | Stored |
| C212A-16 | System circuit voltage below threshold | Stored |

ORC(Air Bag/Occupant Restraint) (1 DTC)

| DTC | Description | Status |
|----------|--|--------|
| B21DD-16 | System circuit voltage below threshold | Stored |

IPC(Instrument Panel Cluster) (2 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B1612-00 | Panel illumination control | Stored |
| B21DD-84 | System voltage - signal below allowable range | Stored |

TPM(Tire Pressure Monitor) (5 DTCs)

| DTC | Description | Status |
|----------|--|--------|
| B21DD-84 | System voltage - signal below allowable range | Stored |
| C0077-00 | Low tire pressure | Stored |
| C1501-96 | Tire pressure sensor 1 component internal failure | Stored |
| C1580-00 | Left/Right side tire pressure sensor location undetermined | Stored |
| C1581-00 | Front/Rear tire pressure sensor location undetermined | Stored |

BCM(Body Controller) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |

RADIO(Radio) (2 DTCs)

| DTC | Description | Status |
|----------|--|--------|
| B157E-00 | Touch screen locked | Stored |
| B210A-16 | System voltage low - circuit voltage below threshold | Stored |

EPS(Electric Power Steering) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| C212A-84 | System voltage - signal below allowable range | Stored |

AFLS(Adaptive Front Lighting System) (4 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| U0121-00 | Lost communication with anti-lock brake system (ABS) control module "A" | Stored |
| B287E-16 | Left headlamp module circuit voltage below threshold | Stored |
| B287F-16 | Right headlamp module circuit voltage below threshold | Stored |
| B1684-77 | Left headlamp leveling motor control - commanded position not reachable | Stored |

PDM(Passenger Door Module) (3 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B21DD-84 | System voltage - signal below allowable range | Stored |
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored |
| B224F-54 | Door module internal - missing calibration | Stored |

ITM(Intrusion Transceiver Module) (2 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B210A-84 | System voltage low - signal below allowable range | Stored |
| U0010-00 | CAN interior bus | Stored |

SCCM(Steering Column Control Module) (2 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| C212A-16 | System circuit voltage below threshold | Stored |
| C2129-16 | Battery voltage - circuit voltage below threshold | Stored |

PTS(Parktronics) (2 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored |
| B21DD-16 | System circuit voltage below threshold | Stored |

DDM(Driver Door Module) (3 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B21DD-84 | System voltage - signal below allowable range | Stored |
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored |
| B173D-11 | Mirror signal lamp control - circuit short to ground | Stored |

HSM(Heated Seat Module) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| B11C1-13 | Steering wheel heater power supply circuit - circuit open | Stored |

RFH(Radio Frequency Hub) (5 DTCs)

| DTC | Description | Status |
|----------|--|--------|
| B21DD-84 | System voltage - signal below allowable range | Stored |
| B1A28-00 | ECM mismatch with SKIM | Stored |
| B1A80-00 | Electronic steering column lock communication performance (Type 2-3) | Stored |
| B2254-00 | Column lock module internal | Stored |
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |

ESM(Electronic Shifter) (5 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| U11C3-00 | ESM lost communication with TCM on D-PT CAN | Stored |
| U0101-08 | Lost communication with TCM - bus signal/message failures | Stored |
| P1C8C-16 | System circuit voltage below threshold | Stored |

| | | |
|----------|---|--------|
| P1C8B-16 | Battery voltage - circuit voltage below threshold | Stored |
| U0402-00 | Implausible data received from TCM | Stored |

EDM(External Disc Module) (1 DTC)

| DTC | Description | Status |
|----------|--------------------------------------|--------|
| B1423-00 | VES DVD read error / inoperable disc | Active |

ACC(Adaptive Cruise Control) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| C2129-16 | Battery voltage - circuit voltage below threshold | Stored |

MSM(Memory Seat/Memory Heated Seat) (2 DTCs)

| DTC | Description | Status |
|----------|--|--------|
| B210A-84 | System voltage low - signal below allowable range | Stored |
| B210D-21 | Battery voltage low - signal amplitude below minimum | Stored |

PLGM(Power Liftgate Module) (8 DTCs)

| DTC | Description | Status |
|----------|---|--------|
| B21DD-16 | System circuit voltage below threshold | Stored |
| B1979-00 | Power liftgate latch cinch - sector switch performance | Stored |
| B197F-13 | Power liftgate latch control 1 - circuit open | Stored |
| B197F-12 | Power liftgate latch control 1 - circuit short to battery | Stored |
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |
| B1978-00 | Power liftgate close direction - sector switch performance | Stored |
| B1977-00 | Power liftgate open direction - sector switch performance | Stored |
| B1975-00 | Power liftgate latch cinch - ratchet secondary switch performance | Stored |

RBSS(Right Blind Spot Sensor) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |

LBSS(Left Blind Spot Sensor) (1 DTC)

| DTC | Description | Status |
|----------|---|--------|
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |

FFCM(Forward Facing Camera Module) (1 DTC)

| DTC | Description | Status |
|----------|--|--------|
| U0418-00 | Implausible data received from brake system control module 1 | Stored |

ASCM(Air Suspension Control Module) (6 DTCs)

| DTC | Description | Status |
|----------|--|--------|
| C212A-16 | System circuit voltage below threshold | Stored |
| C2129-16 | Battery voltage - circuit voltage below threshold | Stored |
| U0415-00 | Invalid data received from anti-lock brake system (ABS) control module "A" | Stored |
| U0401-00 | Implausible data received from ECM/PCM | Stored |
| C1562-98 | Ride height air pump control component/system overtemperature | Stored |
| C1562-13 | Ride height air pump control circuit open | Stored |

Technician Notes

2016335407

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.