

Shop: DEKRA MFC Tel: --Email: --Address: MFC Auction House Kempton Park Report ID: MAXIA20240112111118 Test Time: 2024-01-1211:11:18 Technician: Andrick

. .

JEEP VEHICLE DIAGNOSTIC REPORT

| Vehicle Information | | |
|---|-----------------------------|--|
| /JEEP/WK-Grand cherokee/ | Odometer Reading: 153155 | |
| VIN: 1C4RJFKGXFC721824 | License Plate: DM92LKGP | |
| Customer Information | | |
| Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE | Tel: 0861033572 | |
| Device information | | |
| Scanner: MaxiSys MS906 BT | Serial Number: VB8GJCC01482 | |
| Version: V10.51 | Repair Order Number: | |
| | | |

System Scanned(32)

| System | | Status/DTC |
|--------------------------------------|------|------------|
| ECM(Engine Control Module) | | Q 1 |
| TCM(Transmission Control Module) | | O |
| DTCM(Drive Train Control Module) | | Q 1 |
| ABS(Anti Lock Brakes) | | 3 2 |
| ORC(Air Bag/Occupant Restraint) | | O |
| IPC(Instrument Panel Cluster) | | O |
| TPM(Tire Pressure Monitor) | | Q 4 |
| BCM(Body Controller) | | Q 1 |
| RADIO(Radio) | | Q 1 |
| HVAC(Heat, Ventilation And A/C) | | Q 1 |
| EPS(Electric Power Steering) | | O |
| AFLS(Adaptive Front Lighting System) | ADAS | O |
| PDM(Passenger Door Module) | | 3 2 |
| ITM(Intrusion Transceiver Module) | | Q 1 |
| SCCM(Steering Column Control Module) | | O |
| AMP(Amplifier) | | O |
| PTS(Parktronics) | ADAS | Q 1 |
| ICS(Integrated Center Stack) | | O |
| AUTEL www.autel.com MaxiSys MS906 BT | | Page 1 |

| EEP/WK-Grand cherokee Test Time: 2024-01-12 11:11:18 | Report ID: MAXIA20240112111118 | | | |
|--|--------------------------------|--|--|--|
| DM(Driver Door Module) | Q 2 | | | |
| ISM(Heated Seat Module) | O | | | |
| ES3(Last Row Screen) | Q 1 | | | |
| FH(Radio Frequency Hub) | Q 1 | | | |
| SM(Electronic Shifter) | 3 2 | | | |
| DM(External Disc Module) | O | | | |
| CC(Adaptive Cruise Control) | Q 1 | | | |
| ISM(Memory Seat/Memory Heated Seat) | Q 1 | | | |
| ES2(Second Row Screen) | Q 1 | | | |
| LGM(Power Liftgate Module) | 3 | | | |
| BSS(Right Blind Spot Sensor) | O | | | |
| BSS(Left Blind Spot Sensor) | O | | | |
| FCM(Forward Facing Camera Module) | Q 1 | | | |
| SCM(Air Suspension Control Module) | Q 1 | | | |
| DTC(34) | | | | |
| CM(Engine Control Module) (1 DTC) | | | | |
| TC Description | Status | | | |
| 0117 Engine coolant temperature (ECT) sensor circuit low | Stored | | | |
| TCM(Drive Train Control Module) (1 DTC) | | | | |
| TC Description | Status | | | |
| 0401-00 Implausible data received from ECM/PCM | Stored | | | |
| 3S(Anti Lock Brakes) (2 DTCs) | | | | |
| TC Description | Status | | | |
| 0401-00 Implausible data received from ECM/PCM | Stored | | | |
| 0403-00 Implausible data received from T-Case | Stored | | | |
| TPM(Tire Pressure Monitor) (4 DTCs) | | | | |
| TC Description | Status | | | |
| 1580-00 Left/Right side tire pressure sensor location undetermined | Stored | | | |
| 1581-00 Front/Rear tire pressure sensor location undetermined | Stored | | | |

Tire pressure sensor 3 component internal failure

C1503-96

Stored

Test Time: 2024-01-12 11:11:18

Report ID: MAXIA20240112111118

| | | • | |
|---|---|--------|--|
| C1504-96 | Tire pressure sensor 4 component internal failure | Stored | |
| BCM(Body Con | troller) (1 DTC) | | |
| DTC | Description | Status | |
| B16FB-15 | Right front fog lamp control - circuit short to battery or open | Active | |
| RADIO(Radio) (| (1 DTC) | | |
| DTC | Description | Status | |
| B1562-12 | GPS antenna - circuit short to battery | Stored | |
| HVAC(Heat, Ve | ntilation And A/C) (1 DTC) | | |
| DTC | Description | Status | |
| B11C2-13 | Front mode door 1 control - circuit open | Stored | |
| PDM(Passenge | er Door Module) (2 DTCs) | | |
| DTC | Description | Status | |
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored | |
| B21DD-84 | System voltage - signal below allowable range | Stored | |
| ITM(Intrusion | Fransceiver Module) (1 DTC) | | |
| DTC | Description | Status | |
| B1A3F-00 | ITM arming sequence performance | Stored | |
| PTS(Parktronic | es) (1 DTC) | | |
| DTC | Description | Status | |
| B1291-12 | PTS (Parktronics) sensor 4 - circuit short to battery | Active | |
| DDM(Driver Do | or Module) (2 DTCs) | | |
| DTC | Description | Status | |
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored | |
| B21DD-84 | System voltage - signal below allowable range | Stored | |
| VES3(Last Row | v Screen) (1 DTC) | | |
| DTC | Description | Status | |
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored | |
| RFH(Radio Frequency Hub) (1 DTC) | | | |
| DTC | Description | Status | |
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored | |
| ESM(Electronic Shifter) (2 DTCs) | | | |
| DTC | Description | Status | |
| U1175-00 | Lost ignition status message | Stored | |
| AUTEL www.autel.com MaxiSys MS906 BT Pa | | | |
| | | | |

| /JEEP/WK-Grand | cherokee Test Tir | me: 2024-01-12 11:11:18 | Report ID: MAXIA20240112111118 |
|----------------|---|--------------------------|--------------------------------|
| P1C8B-16 | Battery voltage - circuit voltage below threshold | | Stored |
| ACC(Adaptive | Cruise Control) (1 DTC) | | |
| DTC | Description | | Status |
| C2227-00 | ABS disabled ECU | | Stored |
| MSM(Memory | Seat/Memory Heated Seat) (1 DTC) | | |
| DTC | Description | | Status |
| B210D-21 | Battery voltage low - signal ampl | itude below minimum | Stored |
| VES2(Second | Row Screen) (1 DTC) | | |
| DTC | Description | | Status |
| B2199-16 | Battery voltage - circuit voltage b | elow threshold | Stored |
| PLGM(Power L | .iftgate Module) (8 DTCs) | | |
| DTC | Description | | Status |
| B21DD-16 | System circuit voltage below thre | shold | Stored |
| U0422-00 | Implausible data received from be | ody control module | Stored |
| B2199-16 | Battery voltage - circuit voltage b | elow threshold | Stored |
| B1978-00 | Power liftgate close direction - se | ector switch performance | Stored |
| B197F-13 | Power liftgate latch control 1 - ci | cuit open | Stored |
| B197F-12 | Power liftgate latch control 1 - ci | cuit short to battery | Stored |
| B1977-00 | Power liftgate open direction - se | ctor switch performance | Stored |
| B197A-00 | Power liftgate latch release - sec | tor switch performance | Stored |
| FFCM(Forward | Facing Camera Module) (1 DTC) | | |
| DTC | Description | | Status |
| C14A5-00 | Sensor blinded | | Stored |
| ASCM(Air Susj | pension Control Module) (1 DTC) | | |
| DTC | Description | | Status |
| C1562-98 | Ride height air pump control com overtemperature | ponent/system | Stored |
| | | | |

Test Time: 2024-01-12 11:11:18

Technician Notes 2016226775

Customer name:

Technician:

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.