

Shop Name: --Tel: --Email: --Address: -- Report ID: MAXIA20250724164213 Test Time: 2025-07-24 16:42:13

ne: 2025-07-24 16:42:13 Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/Polo Cross/-- Odometer Reading: 186443 VIN: AAVZZZ6RZCU046651 License Plate: JD33LHGP

Customer Information

Name: MFC Dekra Nedbank Auction House Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01509

Version: V22.50 Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	② 0
03 - Brakes 1	Q 1
08 - Air Conditioning	Q 1
09 - Electronic central electric	3
15 - Airbag	Q 1
17 - Instrument cluster	② 0
19 - Gateway	② 0
25 - Anti-Theft Immobilizer	② 0
44 - Power Steering	Q 2
56 - Radio	Q 1

TOTO (9)

DTC

03 - Brakes 1 (1 DTC)

Description

00532:002	Supply voltage - Lower limit not reached Passive/Sporadic	
08 - Air Condition	oning (1 DTC)	
DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
09 - Electronic	central electric (3 DTCs)	
DTC	Description	Status

Function limitation due to insufficient voltage - Lower

AUTEL www.autel.com

00446:002

MaxiSys MS906 BT

limit not reached

Status

Passive/Sporadic

/Volkswagen/Pol	Cross Test T	ime: 2025-07-24 16:42:13	Report ID: MAXIA2025072416421
01598:000	Drive battery voltage		Passive/Sporadic
01134:000	Alarm horn		Passive/Sporadic
15 - Airbag (1	DTC)		
DTC	Description		Status
U112200	Data bus message implausible		Passive/Sporadic
44 - Power Ste	ering (2 DTCs)		
DTC	Description		Status
U140A00	Terminal 30 Open circuit		Passive/Sporadic
U101100	Supply voltage Voltage too low		Passive/Sporadic
56 - Radio (1 D	OTC)		
DTC	Description		Status
00446:002	Function limitation due to insuff limit not reached	cient voltage - Lower	Passive/Sporadic
Technician No 2016957259	otes		
		Customer name:	
		Technician:	
		Date:	

 $\label{thm:potential} \textbf{Note:Please save a copy of this report for your records}.$

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



ww.autel.com MaxiSys MS906 BT