



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241010140508

Test Time: 2024-10-10 14:05:08

Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--

VIN: AAVZZZ6RZKU004329

Odometer Reading: 125339

License Plate: HR98MKGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V21.00

Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	3
09 - Electronic central electric	4
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	0
25 - Anti-Theft Immobilizer	2
44 - Power Steering	2
56 - Radio	3

DTC (16)

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic



00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic
03156:014	Anti-theft alarm system sensor - Faulty	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

25 - Anti-Theft Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

44 - Power Steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2016565799

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.