



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250505123306
Test Time: 2025-05-05 12:33:06
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU019338
Odometer Reading: 77062
License Plate: KT42DYGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	✓ 0
03 - Brakes 1	✗ 1
04 - Steering Angle Sender	✓ 0
09 - Electronic central electric	✗ 1
15 - Airbag	✗ 1
17 - Instrument cluster	✗ 1
19 - Gateway	✓ 0
25 - Anti-Theft Immobilizer	✗ 1
44 - Power Steering	✗ 1
56 - Radio	✗ 2

DTC (8)

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C102D00	Tire pressure warning	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
-----	-------------	--------



U140000	Function restriction Caused by low voltage	Passive/Sporadic
---------	---	------------------

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes
2016865046

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.