



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250506110128
Test Time: 2025-05-06 11:01:28
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/Polo VIVO/--
VIN: AAVZZZ6SZFU023316

Odometer Reading: 176760
License Plate: DP39DMGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(11)

System	Status/DTC
01 - Engine Control Module 1	 6
03 - Brakes 1	 4
09 - Electronic central electric	 4
15 - Airbag	 4
17 - Instrument cluster	 6
19 - Gateway	 3
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 3
45 - Interior Monitoring	 0
46 - Comfort System Central Control Module	 0
56 - Radio	 0

DTC (31)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
U0415:00/5-0197:000	Invalid Data Received From Anti-Lock Brake System Control Module	Passive/Sporadic
U0001:00/4-9153:000	Databus drivetrain Faulty	Passive/Sporadic
P0571:00/0-1393:000	Cruise/Brake Switch (A) Circ. Malfunction	Active/static



P1570:00/0-5488:000	Engine control unit disabled	Passive/Sporadic
U0423:00/5-0211:000	Invalid Data Received From Instrument Panel Cluster Control Module	Passive/Sporadic
U0146:00/4-9478:000	Lost Communication With Gateway 'A'	Passive/Sporadic

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
00526:011	Brake light switch - Open circuit	Active/static
01312:014	Drive train data bus - Faulty	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic
01317:004	Instrument cluster control module - No signal/communication	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic
01309:049	Power steering control module - No communication	Passive/Sporadic
01314:049	Engine control unit - No communication	Passive/Sporadic
01312:037	Drive train data bus - Faulty	Passive/Sporadic

15 - Airbag (4 DTCs)

DTC	Description	Status
01312:037	Drive train data bus - Faulty	Passive/Sporadic
01317:049	Instrument cluster control module - No communication	Passive/Sporadic
01044:035	Control module incorrectly coded	Passive/Sporadic
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (6 DTCs)

DTC	Description	Status
01312:037	Drive train data bus - Faulty	Passive/Sporadic
01314:049	Engine control unit - No communication	Passive/Sporadic
01316:049	Brake control module - No communication	Passive/Sporadic
01321:049	Airbag control module - No communication	Passive/Sporadic
00457:049	Vehicle Electrical System Control Module - No communication	Passive/Sporadic
01309:049	Power steering control module - No communication	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
-----	-------------	--------

01309:049	Power steering control module - No communication	Passive/Sporadic
01314:049	Engine control unit - No communication	Passive/Sporadic
01312:037	Drive train data bus - Faulty	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
01176:007	Key - Signal too low	Passive/Sporadic

44 - Power Steering (3 DTCs)

DTC	Description	Status
U000100	Powertrain data bus Faulty	Passive/Sporadic
U111100	Function restriction caused by missing message	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes
2016866298

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.