

Shop Name: Dekra MFC Auction House

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250120115116 Test Time: 2025-01-20 11:51:16

Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--

VIN: AAVZZZAWZLU073351

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V21.50

Odometer Reading: 115707km License Plate: KX79LZGP

Tel: 0861033572

Serial Number: VB8GJCC01514

Repair Order Number: --

🔁 System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	3 1
03 - Brakes 1	◎ 0
08 - Air Conditioning	⊘ 0
09 - Electronic central electric	Q 4
15 - Airbag	Q 1
17 - Instrument cluster	Q 2
19 - Gateway	Q 1
44 - Power Steering	Q 1
5F - Information electronics 1	Q 5

▲ DTC (15)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P167E00	Start/stop restart Maximum start time exceeded	Passive/Sporadic
09 - Electroni	c central electric (4 DTCs)	
DTC	Description	Status
B121D15	Left DRL bulb Circuit open or short to positive	Active/static
D10F01F	Left side marker lamp bulb	A ativa /atatia

www.autel.com

B12E815

MaxiSys MS906 BT

Open circuit/short circuit to B+

Active/static

/Volkswagen/AW	/C1 - T-Cross 2019 > Test Time: 2025-01-20 11:51:16	Report ID: MAXIA20250120115116
B12E915	Right side marker lamp bulb Open circuit/short circuit to B+	Active/static
C10CA00	Limp home active	Passive/Sporadic
15 - Airbag (1	DTC)	
DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
17 - Instrumen	t cluster (2 DTCs)	
DTC	Description	Status
B201000	No basic setting	Active/static
B104C29	Key Range/performance	Passive/Sporadic
19 - Gateway (1 DTC)	
DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
44 - Power Ste	ering (1 DTC)	
DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
5F - Informatio	on electronics 1 (5 DTCs)	
DTC	Description	Status
B126D13	Connection between radio and antenna amplifier 1 Open circuit	Active/static
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B106213	Right front bass speaker Open circuit	Active/static
B105F13	Left front bass speaker Open circuit	Active/static

Technician Notes 2016726369

U111100

www.autel.com MaxiSys MS906 BT Page 2

Passive/Sporadic

Function restriction caused by missing message

Test Time: 2025-01-20 11:51:16 Report ID: MAXIA20250120115116

Customer name: _	
Technician: _	
Date: _	
2 3.13.	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com MaxiSys MS906 BT Page 3