

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
 VIN: AAVZZZAWZMU062330

Odometer Reading: 61479km
 License Plate: ND289290

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	 10
03 - Brakes 1	 0
08 - Air Conditioning	 0
09 - Electronic central electric	 6
15 - Airbag	 1
17 - Instrument cluster	 1
19 - Gateway	 2
44 - Power Steering	 1
5F - Information electronics 1	 3
CA - Sunroof control module	 0

DTC (24)

01 - Engine Control Module 1 (10 DTCs)

DTC	Description	Status
P048000	Cooling Fan 1 Control Circuit	Passive/Sporadic
P052400	Engine Oil Pressure Too Low	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
P168200	Powertrain data bus Implausible message from ABS control unit	Passive/Sporadic
P06EF00	Engine Restart Performance	Passive/Sporadic

P190D00	Coolant pump for charge pressure cooler Mechanical malfunction	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic

09 - Electronic central electric (6 DTCs)

DTC	Description	Status
B11E815	Left front turn signal bulb Open circuit/short circuit to B+	Active/static
B121D15	Left DRL bulb Circuit open or short to positive	Active/static
B121E15	Right DRL bulb Circuit open or short to positive	Active/static
B121F15	Left fog lamp bulb Circuit open or short to positive	Active/static
B122015	Right fog lamp bulb Circuit open or short to positive	Active/static
B12E915	Right side marker lamp bulb Open circuit/short circuit to B+	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U111000	Function restriction caused by communication interruption	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U140600	Static current too high	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
B1297F2	Multimedia system display unit 1 Above upper temperature limit	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U111000	Function restriction caused by communication interruption	Passive/Sporadic

Technician Notes

2016255436

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.