



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD

KEMPTON PARK

Report ID: MAXIA20250228094429

Test Time: 2025-02-28 09:44:29

Technician: Andrick

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--

VIN: AAVZZZAWZNU092544

Odometer Reading: 63798km

License Plate: KS69PBG

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Version: V22.00

Serial Number: VB8GJCC01514

Repair Order Number: --

## System Scanned( 16 )

System	Status/DTC
01 - Engine Control Module 1	14
02 - Transmission electronics	0
03 - Brakes 1	0
08 - Air Conditioning	0
09 - Electronic central electric	0
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	1
44 - Power Steering	1
55 - Headlight Regulation	0
5F - Information electronics 1	1
76 - Parking assistance	0
A5 - Front sensor for drivers assistant systems	2
CA - Sunroof control module	0
D6 - Light Control Left 2	0
D7 - Light Control Right 2	0

## DTC ( 21 )

### 01 - Engine Control Module 1 ( 14 DTCs )

DTC	Description	Status
-----	-------------	--------



P227900	Intake air system leakage	Passive/Sporadic
P045800	Evaporative Emission (EVAP) system purge control valve A circuit short	Passive/Sporadic
P044400	Evaporative Emission (EVAP) system purge control valve A circuit open	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P105700	Bank 1, camshaft adjustment, exhaust Open circuit	Passive/Sporadic
P142900	Brake vacuum pump activation Open circuit	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
P017100	Fuel Trim,Bank1 System too Lean	Passive/Sporadic
P019100	Fuel rail pressure sensor A circuit Range/performance	Passive/Sporadic
P001000	'A' Camshaft Position Actuator Circuit/Open (Bank1)	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014800	Fuel Delivery Error	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic

**15 - Airbag ( 1 DTC )**

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

**17 - Instrument cluster ( 1 DTC )**

DTC	Description	Status
B104B31	Key No signal	Passive/Sporadic

**19 - Gateway ( 1 DTC )**

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

**44 - Power Steering ( 1 DTC )**

DTC	Description	Status
-----	-------------	--------

B200FF0 Internal malfunction Passive/Sporadic

**5F - Information electronics 1 ( 1 DTC )**

DTC	Description	Status
B110231	Rearview camera No signal	Passive/Sporadic

**A5 - Front sensor for drivers assistant systems ( 2 DTCs )**

DTC	Description	Status
B200FF2	Internal malfunction	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic

**Technician Notes**

2016781244

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.