

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZPU109927

Odometer Reading: 110745km
License Plate: HCL866L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (18)

System	Status/DTC
01 - Engine Control Module 1	6
02 - Transmission electronics	0
03 - Brakes 1	0
08 - Air conditioning	1
09 - Electronic central electric	2
15 - Airbag	0
17 - Instrument cluster	1
19 - Gateway	1
2B - Steering Column Locking	0
44 - Power steering	1
55 - Headlamp range control	1
5F - Information electronics 1	1
76 - Parking aid	0
A5 - Front sensor for driver assistance systems	0
B7 - Interface for access/start system	0
CA - Sunroof control module	1
D6 - Light control left 2	0
D7 - Light control right 2	0



DTC (15)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
P044400	Evaporative Emission (EVAP) system purge control valve A circuit open	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected No Sub Type Information	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B147918	Remote control vehicle key 1 Insufficient current	Active/static
B147A18	Remote control vehicle key 2 Insufficient current	Active/static

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U111000	Function restriction due to communication interruption	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

55 - Headlamp range control (1 DTC)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

CA - Sunroof control module (1 DTC)

DTC	Description	Status
B157429	Button for sliding roof Range/performance	Passive/Sporadic

Technician Notes

2017295710

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.