

2022 Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2022/Isuzu/D-MAX/4JK1
VIN: ACVNRCHR9H4003060

Odometer Reading: 388575
License Plate: DXX837L

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.43

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned(5)

System	Status/DTC
ECM(Engine Control Module)	1
ABS(Anti-lock Brake System)	3
SRS(Supplemental Restraint System)	0
IMMO(Immobilizer)	0
SCD(Speedometer Control Device)	0



DTC (4)

ECM(Engine Control Module) (1 DTC)

DTC	Description	Status
U0167	Lost communication with vehicle immobilizer control module	Not present

ABS(Anti-lock Brake System) (3 DTCs)

DTC	Description	Status
C0800_03	Voltage drop detection	Not present
C0161_00	Brake switch circuit fault (ABS/ESC)	Not present
C0710_4B	Steering angle sensor (SAS) center position invalid fault	Present

Technician Notes

2016959196

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.