



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250620112536
Test Time: 2025-06-20 11:25:36
Technician: Werner

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVTFR87JMD096494

Odometer Reading: 115015
License Plate: FVM476L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.43

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
ABS(Anti-lock Brake System)	2
SRS(Supplemental Restraint System)	0
IBS(Intelligent Battery System)	2
BCM(Body Control Module)	6
WAM(Wireless Access Module)	0

DTC (10)

ABS(Anti-lock Brake System) (2 DTCs)

DTC	Description	Status
C0020_01	Pump motor electrical fault	Not present
U1840_86	Invalid data received from BCM (stop lamp)	Not present

IBS(Intelligent Battery System) (2 DTCs)

DTC	Description	Status
P065A_09	Generator fail	Not present
P058D_00	Battery voltage low	Not present

BCM(Body Control Module) (6 DTCs)

DTC	Description	Status
C1725_96	Left rear turn signal lamp output circuit component internal fault	Not present
C1724_96	Right rear turn signal lamp output circuit component internal fault	Not present
C172D_12	Left tail lamp output circuit short to battery	Not present
C172C_12	Right tail lamp output circuit short to battery	Not present



C0023_12	Stop lamp output circuit short to battery	Not present
B1707_11	Door lock/unlock output circuit short to ground	Not present

Technician Notes
2016919282

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.