

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVTFR87JMD123812

Odometer Reading: 108043
License Plate: KVP879MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.61

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
ABS(Anti-lock Brake System)	 4
SRS(Supplemental Restraint System)	 0
IBS(Intelligent Battery System)	 2
BCM(Body Control Module)	 6
WAM(Wireless Access Module)	 2

DTC (14)

ABS(Anti-lock Brake System) (4 DTCs)

DTC	Description	Status
P0830_9F	Clutch switch stuck off	Not present
C0020_01	Pump motor electrical fault	Not present
C052E_49	Valve relay internal circuit fault	Not present
U1800_86	Invalid data received from ECM	Not present

IBS(Intelligent Battery System) (2 DTCs)

DTC	Description	Status
P065A_09	Generator fail	Not present
P058B_00	Current detection	Present

BCM(Body Control Module) (6 DTCs)

DTC	Description	Status
C1721_13	Left front turn signal lamp output circuit open	Not present
C1720_13	Right front turn signal lamp output circuit open	Not present
C1726_13	Right headlamp (low beam) output circuit open	Not present
B1707_11	Door lock/unlock output circuit short to ground	Not present
B1707-12	Please refer to vehicle service manual.	Not present

U1851_86	CAN communication or input data fault with Supplemental Restraint System (SRS) control unit	Not present
----------	---	-------------

WAM(Wireless Access Module) (2 DTCs)

DTC	Description	Status
U0064_88	CAN communication fault (CAN bus off)	Not present
U0140_00	Lost communication with BCM	Not present

Technician Notes

2017298526

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.