



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250730154445
Test Time: 2025-07-30 15:44:45
Technician: Clive

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ADMUSRER2C4644073

Odometer Reading: 409918
License Plate: JDY681NW

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.43

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ECM(Engine Control Module)	 2
ABS(Anti-lock Brake System)	 6
SRS(Supplemental Restraint System)	 2
TCCM(Transfer Case Control Module)	 3
BCM(Body Control Module)	 0
IMMO(Immobilizer)	 0

DTC (13)

ECM(Engine Control Module) (2 DTCs)

DTC	Description	Status
P0113	Intake air temperature (IAT) sensor circuit high	Present
P0102	Mass air flow (MAF) circuit input low	Present

ABS(Anti-lock Brake System) (6 DTCs)

DTC	Description	Status
C0040_18	Right front abnormal wheel speed variation B	Not present
C0040_00	Right front abnormal wheel speed variation A	Not present
C0800_03	Voltage drop detection	Not present
C0161_00	Brake switch circuit fault (ABS/ESC)	Not present
U0073_00	Control module communication bus off	Not present
U0102_71	TCCM information invalid error	Not present

SRS(Supplemental Restraint System) (2 DTCs)

DTC	Description	Status
B1325_03	Battery voltage too low	Not present



B101D_30	ECU fault	Not present
----------	-----------	-------------

TCCM(Transfer Case Control Module) (3 DTCs)

DTC	Description	Status
C0306	Motor A or B circuit	Not present
C0327	Limit switch circuit fault	Not present
C0867	System voltage input low	Not present

Technician Notes
2016963494

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.