Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD **KEMPTON PARK**

Report ID: MAXIA20250625113902 Test Time: 2025-06-25 11:39:02

Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--VIN: ADNUSN365U0115554 Odometer Reading: 220870 License Plate: HG78GRGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Repair Order Number: --

Version: V10.20

🔂 System Scanned(5)

System	Status/DTC
Engine	③ 10
ABS	Q 1
Air bag	Q 3
Electric Power Steering (EPS)/DAST 3	Q 2
BCM	Q 3

TOTE (19)

Engine (10 DTCs)

DTC	Description	Status
P0380	Preheating unit diagnosis connection	Current
P0170	Injection program cycle not performed	Current
P0487	Exhaust Gas Recirculation (EGR) valve position sensor circuit	Current
P3264	Water in diesel warning lamp circuit	Past
P0403	Exhaust Gas Recirculation (EGR) command circuit	Current
P2263	Turbo actuator command	Past
P0685	Main relay control circuit	Past
P0231	Low pressure actuator control circuit	Past
P0560	ECU supply voltage	Past
P0530	Refrigerant sensor circuit	Past

ABS (1 DTC)

DTC	Description	Status
C101F	FR LH wheel speed SEN circ	Current

www.autel.com

MaxiSys MS906 BT

Air bag (3 DTC	3)	
DTC	Description	Status
B1007	Drivers front airbag circuit	Past
B1042	ECU supply voltage	Past
B1005	Passenger front airbag circuit	Past
Electric Power S	Steering (EPS)/DAST 3 (2 DTCs)	
DTC	Description	Status
560148	Please refer to vehicle service manual.	
C1606	Motor circuit	Past
BCM (3 DTCs)		
DTC	Description	Status
000100	Please refer to vehicle service manual.	
042000	Please refer to vehicle service manual.	
042000 004002	Please refer to vehicle service manual. Please refer to vehicle service manual.	

Test Time: 2025-06-25 11:39:02

Technician:

Customer name:

Date: ____

Note:Please save a copy of this report for your records.

Report ID: MAXIA20250625113902

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



/Nissan/NP200

www.autel.com MaxiSys MS906 BT Page 2