



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250528150254
Test Time: 2025-05-28 15:02:54
Technician: Sbu

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/SANDERO/--
VIN: ADRBSRAFKUK410748

Odometer Reading: 142275
License Plate: CX11VNGP

Customer Information

Name: Dekra MFC AUCTION HOUSE





Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(4)

System	Status/DTC
Injection	 2
ABS	 1
Airbag / pretensioners	 6
UCH	 4

DTC (13)

Injection (2 DTCs)

DTC	Description	Status
DF124	Destructive misfire	Memory
DF352	Engine immobiliser circuit Immobiliser line fault	Memory

ABS (1 DTC)

DTC	Description	Status
DTC500FED	Front R/H wheel speed sensor circuit Target magnetic/mechanical problem.	Active

Airbag / pretensioners (6 DTCs)

DTC	Description	Status
DTC903446	Airbag locking switch circuit Coherence	Memory
DTC904142	Passenger's airbag status light circuit Open circuit or short circuit to earth	Memory
DTC904248	Computer supply voltage Feed voltage too low	Memory
DTC907C40	Passenger air bag locking status change	Memory



DTC907F20	Replace computer after impact	Active
DTC90804D	Computer	Memory

UCH (4 DTCs)

DTC	Description	Status
DF180	Decoder -> ring connection Short circuit to earth.	Memory
DF184	Impact detected information	Memory
DF272	Coded line circuit Short circuit to earth.	Memory
DF273	Impact connection	Active

Technician Notes
2016894058

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.