



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250129123555  
Test Time: 2025-01-29 12:35:55  
Technician: Sbu

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Corolla/--  
VIN: AHTBC0JEX00008507

Odometer Reading: 204752km  
License Plate: HT43VDGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V11.20

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 8 )

System	Status/DTC
Engine and ECT	13
ABS/VSC/TRC	2
Combination meter	3
Main body	4
Air conditioner	2
Cruise control	0
EMPS	3
Immobilizer	0

## DTC ( 27 )

### Engine and ECT ( 13 DTCs )

DTC	Description	Status
P0502	Vehicle speed sensor (VSS) A circuit low	Pending
P0502	Vehicle speed sensor (VSS) A circuit low	Current
P1229	Fuel pump system	Current
P1272	Fuel pressure regulator circuit	Current
P1603	Engine stall history	Current
P1604	Startability fault	Current
P1608	Engine lack of power	Current
P0502	Vehicle speed sensor (VSS) A circuit low	History
P1604	Startability fault	History
P1229	Fuel pump system	History



P1603	Engine stall history	History
P1272	Fuel pressure regulator circuit	History
P1608	Engine lack of power	History

**ABS/VSC/TRC ( 2 DTCs )**

DTC	Description	Status
C1241	Low or high power supply voltage	Current
C1300	Skid control ECU fault	Current

**Combination meter ( 3 DTCs )**

DTC	Description	Status
U0129	Lost communication with brake system control module	History
U0131	Lost communication with power steering control module	History
B1507	Turn signal circuit open	History

**Main body ( 4 DTCs )**

DTC	Description	Status
B2321	Driver door motor ECU communication stop	History
U0100	Lost communication with ECM/PCM/EV "A"	History
U0151	Lost communication with restraints control module	History
U0155	Lost communication with instrument panel cluster (IPC) control module	History

**Air conditioner ( 2 DTCs )**

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0155	Lost communication with instrument panel cluster (IPC) control module	History

**EMPS ( 3 DTCs )**

DTC	Description	Status
C1541	Vehicle speed signal	Current
C1541	Vehicle speed signal	History
C1554	Power supply relay failure	History

**Technician Notes**

2016739385

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.