



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250327172716
Test Time: 2025-03-27 17:27:16
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTGA3DD800966934

Odometer Reading: 110962km
License Plate: JJB964MP

Customer Information

Name: Dekra MFC AUCTION HOUSE










Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 3
SRS airbag	 0
Combination meter	 1
Air conditioner	 1
Navigation system	 2
4WD	 1
Cruise control	  0

DTC (10)

Engine and ECT (2 DTCs)

DTC	Description	Status
P2716	Pressure control solenoid D electrical	Current
P2716	Pressure control solenoid D electrical	History

ABS/VSC/TRC (3 DTCs)

DTC	Description	Status
C1241	Low or high power supply voltage	History
C1407	Right rear speed sensor circuit open or short	History
C1408	Left rear speed sensor circuit open or short	History

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History



Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Navigation system (2 DTCs)

DTC	Description	Status
U0129	Vehicle stability control (VSC) ECB ECU communication	History
U0100	Engine/EV ECU communication	History

4WD (1 DTC)

DTC	Description	Status
P17C0	Rear differential lock solenoid circuit low	History

Technician Notes

2016816465

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.