

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTJB8DBX04573847

Odometer Reading: 172130km
License Plate: KSM979MP

Customer Information

Name: MFC Dekra Nedbank Auction House







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.40

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 1
SRS airbag	 2
Combination meter	 0
4WD	 1
Immobilizer	 0

DTC (4)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

4WD (1 DTC)

DTC	Description	Status
P17CC	Rear differential lock control switch stuck in on position	History

Technician Notes

2016996176

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.