



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250225113233
Test Time: 2025-02-25 11:32:33
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTJB8DC904726727

Odometer Reading: 245062km
License Plate: JSK456MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine and ECT	✓ 0
ABS/VSC/TRC	✗ 1
SRS airbag	✓ 0
Combination meter	✓ 0
Cruise control	ADAS ✓ 0
4WD	✗ 1
Navigation system	✗ 2
Immobilizer	✓ 0

DTC (4)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	History

4WD (1 DTC)

DTC	Description	Status
P17BC	Rear differential lock position switch stuck in on position	History

Navigation system (2 DTCs)

DTC	Description	Status
U0100	Engine/EV ECU communication	History
C1622	Rear camera disconnected	History

Technician Notes

2016776356



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.