



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250813090753
Test Time: 2025-08-13 09:07:53
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTKB3CD002650649

Odometer Reading: 134459km
License Plate: FVL735L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.40

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
Engine and transmission	0
SRS airbag	1
Combination meter	1
Brake	0
Navigation system	2
Clearance sonar	2
Central gateway	0
PPS	2
4WD	1
Radar cruise 1	0

DTC (9)

SRS airbag (1 DTC)

DTC	Description	Status
B1821	Side squib (right) circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Navigation system (2 DTCs)

DTC	Description	Status
U0100	Engine/EV electronic control unit(ECU) communication	History



U0129

Vehicle stability control (VSC) engine control box(ECB)
electronic control unit(ECU) communication

History

Clearance sonar (2 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM 'A'	History
U0101	Lost communication with transmission control module (TCM)	History

PPS (2 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed
U012987	Lost communication with brake system control module missing message	Confirmed

4WD (1 DTC)

DTC	Description	Status
U0122	Lost communication with vehicle dynamic control (VDC) module	History

Technician Notes

2016977595

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.