



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250620095949
Test Time: 2025-06-20 09:59:49
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTKB8CD602961130

Odometer Reading: 415219km
License Plate: MF09PPGP

Customer Information

Name: Dekra MFC AUCTION HOUSE








Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 3
SRS airbag	 0
Combination meter	 0
Cruise control	  0
4WD	 2

DTC (5)

ABS/VSC/TRC (3 DTCs)

DTC	Description	Status
C1241	Low or high power supply voltage	Current
C1405	Right front speed sensor circuit open or short	Current
C1406	Left front speed sensor circuit open or short	Current

4WD (2 DTCs)

DTC	Description	Status
P17A0	Automatic disconnecting differential motor control circuit open	Current
P17A0	Automatic disconnecting differential motor control circuit open	History

Technician Notes

2016918984



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.