



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250506152714
Test Time: 2025-05-06 15:27:14
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTKB8CD702975246

Odometer Reading: 198902km
License Plate: HBJ289L

Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine and ECT	 4
ABS/VSC/TRC	 1
SRS airbag	 0
Combination meter	 2
Navigation system	 0
Immobilizer	 0

DTC (7)

Engine and ECT (4 DTCs)

DTC	Description	Status
P1605	Rough idling	Current
P1608	Engine lack of power	Current
P1605	Rough idling	History
P1608	Engine lack of power	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	History

Combination meter (2 DTCs)

DTC	Description	Status
U0129	Lost communication with brake system control module	History
B1508	Turn signal/hazard flasher circuit short	History

Technician Notes
2016866871



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.