



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250422114133
Test Time: 2025-04-22 11:41:33
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P007131626

Odometer Reading: 251154km
License Plate: N O N E re g

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	0
ABS/VSC/TRC	6
SRS airbag	3
Combination meter	2
Immobilizer	0

DTC (11)

ABS/VSC/TRC (6 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1404	Fault in rear speed sensor left circuit	History
C1417	Ignition 1 voltage supply too high	History
C1424	Master cylinder pressure sensor zero point output	History
C1425	Stop switch circuit open	History

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (2 DTCs)

DTC	Description	Status
B1507	Turn signal circuit open	History



B1508

Turn signal/hazard flasher circuit short

History

Technician Notes

2016850176

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.